



Coordinate Collision Diagram Report

1/1/2014 to 12/31/2014

For XCoordinate 2436672.81821834 : YCoordinate 1139298.35304309 | Foot Tolerance : 250 | County : Sangamon | Intersection Related: Intersections | *See Notes at End of Report.

Date	Weather	Roadway	Injuries			Killed	Type of Crash	Light Condition	Mile	XCoordinate	Vehicle Type	DIRP	Maneuver	Event 1	Loc 1	Event 2	Loc 2	Event 3	Loc 3	Unit
20140017935			----	A	B	----	C													
2/19/2014 11:18 AM	Clear	Wet	0	0	0	0	Front to Rear	Daylight	0.00	2436672.82090312 1139298.02886328	Passenger	East	Slow/Stop In Traffic	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
201400168513																				
3/23/2014 6:20 PM	Clear	Dry	1	1	0	0	Turning	Daylight	0.00	2436672.81821834 1139298.35304309	Passenger	East	Turning Left	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
201400182897																				
3/29/2014 11:52 AM	Cloudy/Overca st	Dry	0	0	0	0	Angle	Daylight	0.00	2436672.81821834 1139298.35304309	Pickup	East	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
201400205301																				
4/6/2014 11:25 AM	Clear	Dry	0	0	0	0	Turning	Daylight	0.00	2436672.81821834 1139298.35304309	Passenger	North	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
201400209288																				
4/9/2014 11:04 AM	Clear	Dry	0	2	0	0	Angle	Daylight	0.00	2436672.81876317 1139298.26726009	Passenger	West	Straight Ahead	Motor Vehicle In Traffic	Intersectio n	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	1
201400209288																				
4/9/2014 11:04 AM	Clear	Dry	0	2	0	0	Angle	Daylight	0.00	2436672.81876317 1139298.26726009	Passenger	West	Straight Ahead	Motor Vehicle In Traffic	Intersectio n	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	1
201400209288																				
4/9/2014 11:04 AM	Clear	Dry	0	2	0	0	Angle	Daylight	0.00	2436672.81876317 1139298.26726009	SUV	South	Straight Ahead	Motor Vehicle In Traffic	Intersectio n	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	2



Coordinate Collision Diagram Report

1/1/2014 to 12/31/2014

For XCoordinate 2436672.81821834 : YCoordinate 1139298.35304309 | Foot Tolerance : 250 | County : Sangamon | Intersection Related: Intersections | *See Notes at End of Report.

Date	Weather	Roadway	A	Injuries B	C	Killed	Type of Crash	Light Condition	Mile	XCoordinate	Vehicle Type	DIRP	Maneuver	Event 1	Loc 1	Event 2	Loc 2	Event 3	Loc 3	Unit
201400353649																				
7/21/2014 2:01 PM	Clear	Dry	0	0	1	0	Fixed Object	Daylight	0.00	2436672.81821834 1139298.35304309	Passenger	East	Sliding/Control Loss	Ran Off Roadway	Off Pavement - Right	Curb	Off Pavement - Right	Motor Vehicle in Pavement (Roadway)	(UNK)	1
201400130229																				
7/27/2014 10:19 AM	Clear	Dry	1	0	0	0	Angle	Daylight	0.00	2436672.82116987 1139297.99667659	Passenger	North	Straight Ahead	Motor Vehicle in Traffic	Intersection (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
201400384554																				
8/31/2014 5:44 PM	Clear	Dry	0	0	0	0	Angle	Daylight	0.00	2436672.81821834 1139298.35304309	Passenger	East	Straight Ahead	Motor Vehicle in Traffic	Intersection (UNK)	(UNK)	(UNK)	(UNK)	(UNK)	1
201400393828																				
9/15/2014 8:00 AM	Clear	Wet	0	0	0	0	Turning	Daylight	0.00	2436672.81821834 1139298.35304309	Pickup	West	Turning Left	Motor Vehicle in Pavement (Roadway)	On Pavement	(UNK)	(UNK)	(UNK)	(UNK)	1
201400402418																				
9/27/2014 12:45 PM	Clear	Dry	0	2	0	0	Angle	Daylight	0.00	2436672.81821834 1139298.35304309	Passenger	East	Slow/Stop in Traffic	Motor Vehicle in Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
201400402418																				
9/27/2014 12:45 PM	Clear	Dry	0	2	0	0	Angle	Daylight	0.00	2436672.81821834 1139298.35304309	Passenger	North	Straight Ahead	Motor Vehicle in Traffic	Intersection (UNK)	(UNK)	(UNK)	(UNK)	(UNK)	1
201400402418																				
9/27/2014 12:45 PM	Clear	Dry	0	2	0	0	Angle	Daylight	0.00	2436672.81821834 1139298.35304309	Passenger	East	Straight Ahead	Motor Vehicle in Traffic	Intersection (UNK)	(UNK)	(UNK)	(UNK)	(UNK)	2



Coordinate Collision Diagram Report

1/1/2014 to 12/31/2014

For XCoordinate 2436672.81821834 : YCoordinate 1139298.35304309 | Foot Tolerance : 250 | County : Sangamon | Intersection Related: Intersections | *See Notes at End of Report.

Date	Weather	Roadway	Injures A B C	Killed	Type of Crash	Light Condition	Mile	XCoordinate	Vehicle Type	DIRP	Maneuver	Event 1	Loc 1	Event 2	Loc 2	Event 3	Loc 3	Unit
201400297390																		
11/15/2014 12:13 PM	Clear	Dry	0	0	0	Front to Rear	Daylight	0.00	2436672.80627631 1139298.3528174	Passenger	East	Straight Ahead	Motor Vehicle In Pavement Traffic (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
201400447812																		
12/4/2014 3:35 PM	Clear	Dry	0	0	0	Turning	Daylight	0.00	2436672.81821834 1139298.35304309	Van/Mini-Van	West	Turning Left	Motor Vehicle In Pavement Traffic (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
201400451040																		
12/14/2014 8:49 AM	Cloudy/Overcast	Wet	1	0	1	Angle	Daylight	0.00	2436672.81821834 1139298.35304309	Passenger	North	Straight Ahead	Motor Vehicle In Pavement Traffic (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
201400454724																		
12/23/2014 5:05 PM	Clear	Dry	0	0	0	Turning	Darkness, Lighted Road	0.00	2436672.81821834 1139298.35304309	Passenger	East	Straight Ahead	Motor Vehicle In Pavement Traffic (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
201400454724																		
12/23/2014 5:05 PM	Clear	Dry	0	0	0	Turning	Darkness, Lighted Road	0.00	2436672.81821834 1139298.35304309	Passenger	West	Straight Ahead	Motor Vehicle In Pavement Traffic (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2



Coordinate Collision Diagram Report

1/1/2014 to 12/31/2014

For XCoordinate 2436672.81821834 : YCoordinate 1139298.35304309 | Foot Tolerance : 250 | County : Sangamon | Intersection Related: Intersections | *See Notes at End of Report.

TOTAL CRASHES	FATAL CRASHES	A INJURY CRASHES	B INJURY CRASHES	C INJURY CRASHES	PROPERTY DAMAGE CRASHES	TOTAL KILLED	TOTAL INJURED	A INJURIES	B INJURIES	C INJURIES
18	0	3	3	1	11	0	12	3	6	3

Type of Crash	Total	%	Day of Wk	Total	%	Hour of Day	Total	%	Vehicle Type	Total	%
Angle	6	33.3%	Monday	2	11.1%	08 AM	2	11.1%	Motorcycle	1	2.6%
Fixed Object	1	5.6%	Tuesday	3	16.7%	10 AM	1	5.6%	Passenger	27	71.1%
Front to Rear	3	16.7%	Wednesday	2	11.1%	11 AM	4	22.2%	Pickup	3	7.9%
Turning	8	44.4%	Thursday	2	11.1%	Noon	3	16.7%	SUV	4	10.5%
TOTAL:	18		Saturday	4	22.2%	2 PM	3	16.7%	Van/Min-Van	3	7.9%
			Sunday	5	27.8%	3 PM	2	11.1%	TOTAL:	38	
			TOTAL:	18		5 PM	2	11.1%			
						6 PM	1	5.6%			
						TOTAL:	18				

Weather Cond	Total	%	Light Cond	Total	%	Road Surface	Total	%	DIRP	Total	%
Clear	14	77.8%	Darkness, Lighted Road	1	5.6%	Dry	13	72.2%	East	14	36.8%
Cloudy/Overcast	2	11.1%	Daylight	17	94.4%	Wet	5	27.8%	North	10	26.3%
Rain	2	11.1%	TOTAL:	18		TOTAL:	18		Northeast	2	5.3%
TOTAL:	18								Northwest	1	2.6%
									South	3	7.9%
									West	8	21.1%
									TOTAL:	38	



Coordinate Collision Diagram Report

1/1/2014 to 12/31/2014

For XCoordinate 2436672.81821834 : YCoordinate 1139298.35304309 | Foot Tolerance : 250 | County : Sangamon | Intersection Related: Intersections | *See Notes at End of Report.

Notes

DISCLAIMER: The motor vehicle crash data referenced herein was provided by the Illinois Department of Transportation. Any conclusions drawn from analysis of the aforementioned data are the sole responsibility of the data recipient(s). Additionally, for coding years 2015 to present, the Bureau of Data Collection uses the exact latitude/longitude supplied by the investigating law enforcement agency to locate crashes. Therefore, location data may vary in previous years since data prior to 2015 was physically located by bureau personnel.



Coordinate Collision Diagram Report

1/1/2015 to 12/31/2015

For XCoordinate 2436672.81821834 : YCoordinate 1139298.35304309 | Foot Tolerance : 250 | County : Sangamon | Intersection Related: Intersections | *See Notes at End of Report.

Date	Weather	Roadway	----- A	Injures B	----- C	Killed	Type of Crash	Light Condition	Mile	XCoordinate YCoordinate	Vehicle Type	DIRP	Maneuver	Event 1	Loc 1	Event 2	Loc 2	Event 3	Loc 3	Unit
201501173065	Clear	Dry	0	0	0	0	Turning	Daylight	0.00	2436672.94816879 1139298.8219452	Passenger	Southeast	Turning Left	Motor Vehicle In Pavement Traffic (Roadway)	On	(UNK)	(UNK)	(UNK)	(UNK)	1
1/7/2015 3:45 PM	Clear	Dry	0	0	0	0	Turning	Daylight	0.00	2436672.81821834 1139298.34822297	Passenger	North	Straight Ahead	Motor Vehicle In Pavement Traffic (Roadway)	On	(UNK)	(UNK)	(UNK)	(UNK)	2
201501173070	Clear	Dry	0	0	0	0	Turning	Darkness, Lighted Road	0.00	2436672.41423124 1139299.1612296	SUV	West	Turning Left	Motor Vehicle In Pavement Traffic (Roadway)	On	(UNK)	(UNK)	(UNK)	(UNK)	1
1/7/2015 6:37 PM	Clear	Dry	0	0	0	0	Turning	Darkness, Lighted Road	0.00	2436672.97637429 1139298.44366128	SUV	East	Straight Ahead	Motor Vehicle In Pavement Traffic (Roadway)	On	(UNK)	(UNK)	(UNK)	(UNK)	2
201501188368	Clear	Wet	0	0	0	0	Turning	Daylight	0.00	2436672.97637429 1139298.44366128	SUV	East	Turning Left	Motor Vehicle In Pavement Traffic (Roadway)	On	(UNK)	(UNK)	(UNK)	(UNK)	1
1/16/2015 8:40 AM	Clear	Wet	0	0	0	0	Turning	Daylight	0.00	2436672.97637429 1139298.44366128	SUV	North	Straight Ahead	Motor Vehicle In Pavement Traffic (Roadway)	On	(UNK)	(UNK)	(UNK)	(UNK)	2
201501295860	Cloudy/Overcast	Dry	0	0	0	0	Front to Rear	Daylight	0.00	2436672.81821834 1139298.35304309	Passenger	South	Straight Ahead	Motor Vehicle In Pavement Traffic (Roadway)	On	(UNK)	(UNK)	(UNK)	(UNK)	1
2/11/2015 10:42 AM	Cloudy/Overcast	Dry	0	0	0	0	Front to Rear	Daylight	0.00	2436672.81821834 1139298.35304309	Passenger	South	Straight Ahead	Motor Vehicle In Pavement Traffic (Roadway)	On	(UNK)	(UNK)	(UNK)	(UNK)	2
201501305959	Clear	Dry	0	1	0	0	Turning	Daylight	0.00	2436672.56317821 1139298.34822297	Passenger	South	Turning Left	Motor Vehicle In Pavement Traffic (Roadway)	On	(UNK)	(UNK)	(UNK)	(UNK)	1
3/30/2015 2:23 PM	Clear	Dry	0	1	0	0	Turning	Daylight	0.00	2436672.56317821 1139298.34822297	Passenger	West	Straight Ahead	Motor Vehicle In Pavement Traffic (Roadway)	On	(UNK)	(UNK)	(UNK)	(UNK)	2



Coordinate Collision Diagram Report

1/1/2015 to 12/31/2015

For XCoordinate 2436672.81821834 : YCoordinate 1139298.35304309 | Foot Tolerance : 250 | County : Sangamon | Intersection Related: Intersections | *See Notes at End of Report.

Date	Weather	Roadway	A	Injures B	C	Killed	Type of Crash	Light Condition	Mile	XCoordinate YCoordinate	Vehicle Type	DIRP	Maneuver	Event 1	Loc 1	Event 2	Loc 2	Event 3	Loc 3	Unit
201501438132																				
5/1/2015 11:54 AM	Clear	Dry	0	0	0	0	Turning	Daylight	0.00	2436672.78013827 1139298.3523234	Passenger	Southwest	Turning Left	Motor Vehicle In n Traffic	Intersectio	(UNK)	(UNK)	(UNK)	(UNK)	1
201501088250																				
5/5/2015 1:51 PM	Clear	Dry	0	0	0	0	Turning	Daylight	0.00	2436672.81182983 1139298.35292235	Other Vehicle With Trailer	East	Turning Right	Motor Vehicle In Pavement Traffic (Roadway)	On	(UNK)	(UNK)	(UNK)	(UNK)	1
201501445788																				
5/6/2015 4:32 PM	Clear	Dry	0	0	0	0	Turning	Daylight	0.00	2436672.81821834 1139298.35304309	Pickup	West	Turning Right	Motor Vehicle In Pavement Traffic (Roadway)	On	(UNK)	(UNK)	(UNK)	(UNK)	2
201501419956																				
5/18/2015 4:30 PM	Clear	Dry	0	0	0	0	Front to Rear	Daylight	0.00	2436672.79680986 1139298.35263849	SUV	Northwest	Turning Left	Motor Vehicle In Pavement Traffic (Roadway)	On	(UNK)	(UNK)	(UNK)	(UNK)	1
201501419977																				
5/19/2015 2:52 PM	Clear	Dry	0	0	0	0	Angle	Daylight	0.00	2436672.81821834 1139298.35304309	Passenger	South	Changing Lanes	Motor Vehicle In Pavement Traffic (Roadway)	On	(UNK)	(UNK)	(UNK)	(UNK)	1
201501419977																				
5/19/2015 2:52 PM	Clear	Dry	0	0	0	0	Angle	Daylight	0.00	2436672.81821834 1139298.35304309	Passenger	South	Straight Ahead	Motor Vehicle In Pavement Traffic (Roadway)	On	(UNK)	(UNK)	(UNK)	(UNK)	2
201501419977																				
5/19/2015 2:52 PM	Clear	Dry	0	0	0	0	Angle	Daylight	0.00	2436672.81821834 1139298.35304309	Passenger	East	Straight Ahead	Motor Vehicle In Pavement Traffic (Roadway)	On	(UNK)	(UNK)	(UNK)	(UNK)	1
201501419977																				
5/19/2015 2:52 PM	Clear	Dry	0	0	0	0	Angle	Daylight	0.00	2436672.81821834 1139298.35304309	Passenger	South	Straight Ahead	Motor Vehicle In Pavement Traffic (Roadway)	On	(UNK)	(UNK)	(UNK)	(UNK)	2



Coordinate Collision Diagram Report

1/1/2015 to 12/31/2015

For XCoordinate 2436672.81821834 : YCoordinate 1139298.35304309 | Foot Tolerance : 250 | County : Sangamon | Intersection Related: Intersections | *See Notes at End of Report.

Date	Weather	Roadway	A	Injures B	C	Killed	Type of Crash	Light Condition	Mile	XCoordinate YCoordinate	Vehicle Type	DIRP	Maneuver	Event 1	Loc 1	Event 2	Loc 2	Event 3	Loc 3	Unit
201501422376																				
5/28/2015 7:00 PM	Rain	Wet	0	0	0	0	Turning	Daylight	0.00	2436672.81821834 1139298.35304309	Pickup	Northwest	Turning Left	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
201501453159																				
7/1/2015 7:51 PM	Clear	Dry	0	0	0	0	Turning	Dusk	0.00	2436672.88277693 1139298.35046332	Passenger	East	Slow/Stop In Traffic	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
201501425650																				
7/14/2015 1:54 PM	Clear	Dry	0	0	1	0	Turning	Daylight	0.00	2436672.73144186 1139298.35140306	Passenger	South	Turning Left	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
201501311076																				
7/16/2015 4:14 PM	Clear	Dry	0	0	2	0	Turning	Daylight	0.00	2436672.79890129 1139298.35267801	Passenger	North	Turning Left	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
201501311146																				
7/17/2015 6:51 AM	Clear	Dry	1	0	0	0	Angle	Daylight	0.00	2436672.81821834 1139298.35304309	Passenger	West	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
201501311146																				
7/17/2015 6:51 AM	Clear	Dry	1	0	0	0	Angle	Daylight	0.00	2436672.81821834 1139298.35304309	Pickup	North	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2



Coordinate Collision Diagram Report

1/1/2015 to 12/31/2015

For XCoordinate 2436672.81821834 : YCoordinate 1139298.35304309 | Foot Tolerance : 250 | County : Sangamon | Intersection Related: Intersections | *See Notes at End of Report.

Date	Weather	Roadway	Injuries			Killed	Type of Crash	Light Condition	Mile	XCoordinate YCoordinate	Vehicle Type	DIRP	Maneuver	Event 1	Loc 1	Event 2	Loc 2	Event 3	Loc 3	Unit
201501464113																				
8/7/2015 7:30 AM	Clear	Dry	0	0	0	0	Turning	Daylight	0.00	2436672.81821834 1139298.35304309	Pickup	East	Turning Left	Motor Vehicle in n Traffic	Interseccio	(UNK)	(UNK)	(UNK)	(UNK)	1
20150146426																				
9/3/2015 10:23 AM	Clear	Dry	0	0	0	0	Turning	Daylight	0.00	2436672.81821834 1139298.35304309	Passenger	South	Turning Left	Motor Vehicle in n Traffic	Interseccio	(UNK)	(UNK)	(UNK)	(UNK)	1
201501313899																				
9/4/2015 3:11 PM	Clear	Dry	1	0	0	0	Turning	Daylight	0.00	2436672.63945997 1139298.34966465	Passenger	North	Straight Ahead	Motor Vehicle in n Traffic	Interseccio	(UNK)	(UNK)	(UNK)	(UNK)	2
201501314176																				
9/7/2015 8:06 PM	Clear	Dry	2	0	0	0	Angle	Darkness, Lighted Road	0.00	2436672.38313174 1139298.34482019	Passenger	West	Straight Ahead	Motor Vehicle in Pavement Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
201501467882																				
9/8/2015 10:38 PM	Clear	Dry	0	0	0	0	Front to Rear	Darkness, Lighted Road	0.00	2436672.81821834 1139298.35304309	Van/Mini-Van	South	Slow/Stop In Traffic	Motor Vehicle in Pavement Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
201501467882																				
9/8/2015 10:38 PM	Clear	Dry	0	0	0	0	Front to Rear	Darkness, Lighted Road	0.00	2436672.81821834 1139298.35304309	Van/Mini-Van	South	Straight Ahead	Motor Vehicle in Pavement Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2



Coordinate Collision Diagram Report

1/1/2015 to 12/31/2015

For XCoordinate 2436672.81821834 : YCoordinate 1139298.35304309 | Foot Tolerance : 250 | County : Sangamon | Intersection Related: Intersections | *See Notes at End of Report.

Date	Weather	Roadway	A	Injuries B	C	Killed	Type of Crash	Light Condition	Mile	XCoordinate YCoordinate	Vehicle Type	DIRP	Maneuver	Event 1	Loc 1	Event 2	Loc 2	Event 3	Loc 3	Unit
201501471342																				
9/27/2015 2:18 PM	Clear	Dry	0	0	0	0	Turning	Daylight	0.00	2436672.59108627 1139298.34875042	Passenger	West	Turning Left	Motor Vehicle In n Traffic	Intersectio	(UNK)	(UNK)	(UNK)	(UNK)	1
201501473826																				
10/11/2015 5:46 PM	Clear	Dry	0	0	0	0	Turning	Daylight	0.00	2436672.81821834 1139298.35304309	Passenger	North	Turning Left	Motor Vehicle In n Traffic	Intersectio	(UNK)	(UNK)	(UNK)	(UNK)	1
201501481926																				
11/15/2015 8:25 AM	Clear	Dry	0	0	0	0	Front to Rear	Daylight	0.00	2436647.00682647 1139297.86522133	Passenger	East	Straight Ahead	Motor Vehicle In Pavement Traffic	On (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
201501482461																				
11/17/2015 8:04 PM	Rain	Wet	0	0	0	0	Front to Rear	Darkness, Lighted Road	0.00	2436672.32721951 1139298.34376347	Pickup	South	Straight Ahead	Motor Vehicle In Pavement Traffic	On (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
201501485452																				
11/23/2015 5:10 PM	Clear	Dry	0	0	0	0	Turning	Daylight	0.00	2436672.81821834 1139298.35304309	Passenger	South	Straight Ahead	Motor Vehicle In Pavement Traffic	On (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
201501485452																				
11/23/2015 5:10 PM	Clear	Dry	0	0	0	0	Turning	Daylight	0.00	2436672.81821834 1139298.35304309	Passenger	West	Slow/Stop In Traffic	Motor Vehicle In Pavement Traffic	On (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	3



Coordinate Collision Diagram Report

1/1/2015 to 12/31/2015

For XCoordinate 2436672.81821834 : YCoordinate 1139298.35304309 | Foot Tolerance : 250 | County : Sangamon | Intersection Related: Intersections | *See Notes at End of Report.

Date	Weather	Roadway	Injuries			Killed	Type of Crash	Light Condition	Mile	XCoordinate	YCoordinate	Vehicle Type	DIRP	Maneuver	Event 1	Loc 1	Event 2	Loc 2	Event 3	Loc 3	Unit

A B C *****																					
201501494043																					
12/30/2015 3:30 PM	Clear	Dry	0	0	0	0	Turning	Daylight	0.00	2436672.62874146	1139298.34946208	Van/Mini-Van	East	Turning Left	Motor Vehicle in n Traffic	Intersectio n	(UNK)	(UNK)	(UNK)	(UNK)	1
												SUV	North	Straight Ahead	Motor Vehicle in n Traffic	Intersectio n	(UNK)	(UNK)	(UNK)	(UNK)	2



Coordinate Collision Diagram Report

1/1/2015 to 12/31/2015

For XCoordinate 2436672.81821834 : YCoordinate 1139298.35304309 | Foot Tolerance : 250 | County : Sangamon | Intersection Related: Intersections | *See Notes at End of Report.

TOTAL CRASHES	FATAL CRASHES	A INJURY CRASHES	B INJURY CRASHES	C INJURY CRASHES	PROPERTY DAMAGE CRASHES	TOTAL KILLED	TOTAL INJURED	A INJURIES	B INJURIES	C INJURIES
26	0	3	1	2	20	0	8	4	1	3

Type of Crash	Total	%	Day of Wk	Total	%	Hour of Day	Total	%	Vehicle Type	Total	%
Angle	3	11.5%	Monday	4	15.4%	06 AM	1	3.8%	Other Vehicle With Trailer	1	1.8%
Front to Rear	5	19.2%	Tuesday	5	19.2%	07 AM	1	3.8%	Passenger	37	67.3%
Turning	18	69.2%	Wednesday	6	23.1%	08 AM	2	7.7%	Pickup	7	12.7%
TOTAL:	26		Thursday	3	11.5%	10 AM	2	7.7%	SUV	6	10.9%
			Friday	5	19.2%	11 AM	1	3.8%	Unknown	1	1.8%
			Sunday	3	11.5%	1 PM	2	7.7%	Van/Mini-Van	3	5.5%
			TOTAL:	26		2 PM	3	11.5%	TOTAL:	55	
						3 PM	3	11.5%			
						4 PM	3	11.5%			
						5 PM	2	7.7%			
						6 PM	2	7.7%			
						7 PM	2	7.7%			
						8 PM	1	3.8%			
						10 PM	1	3.8%			
						TOTAL:	26				
Weather Cond	Total	%	Light Cond	Total	%	Road Surface	Total	%	DIRP	Total	%
Clear	23	88.5%	Darkness, Lighted Road	4	15.4%	Dry	23	88.5%	East	11	20.0%
Cloudy/Overcast	1	3.8%	Daylight	21	80.8%				North	11	20.0%



Coordinate Collision Diagram Report

1/1/2015 to 12/31/2015

For XCoordinate 2436672.81821834 : YCoordinate 1139298.35304309 | Foot Tolerance : 250 | County : Sangamon | Intersection Related: Intersections | *See Notes at End of Report.

Weather Cond	Total	%	Light Cond	Total	%	Road Surface	Total	%	D/RP	Total	%
Rain	2	7.7%	Dusk	1	3.8%	Wel	3	11.5%	Northeast	1	1.8%
TOTAL:	26		TOTAL:	26		TOTAL:	26		Northwest	3	5.5%
									South	16	29.1%
									Southeast	3	5.5%
									Southwest	1	1.8%
									West	9	16.4%
									TOTAL:	55	



Coordinate Collision Diagram Report

1/1/2015 to 12/31/2015

For XCoordinate 2436672.81821834 : YCoordinate 1139298.35304309 | Foot Tolerance : 250 | County : Sangamon | Intersection Related: Intersections | *See Notes at End of Report.

Notes

DISCLAIMER: The motor vehicle crash data referenced herein was provided by the Illinois Department of Transportation. Any conclusions drawn from analysis of the aforementioned data are the sole responsibility of the data recipient(s). Additionally, for coding years 2015 to present, the Bureau of Data Collection uses the exact latitude/longitude supplied by the investigating law enforcement agency to locate crashes. Therefore, location data may vary in previous years since data prior to 2015 was physically located by bureau personnel.



Coordinate Collision Diagram Report

1/1/2016 to 12/31/2016

For XCoordinate 2436672.81821834 : YCoordinate 1139298.35304309 | Foot Tolerance : 250 | County : Sangamon | Intersection Related: Intersections | *See Notes at End of Report.

Date	Weather	Roadway	Injuries			Killed	Type of Crash	Light Condition	Mile	XCoordinate	Vehicle Type	DIRP	Maneuver	Event 1	Loc 1	Event 2	Loc 2	Event 3	Loc 3	Unit
201601346159			----	A	B	----	C													
2/2/2016 5:31 PM	Rain	Dry	0	0	0	0	Turning	Dusk	0.00	2436672.829106 1139298.35321225	Pickup	South	Turning Left	Motor Vehicle in Pavement Traffic	On (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
											Pickup	East	Straight Ahead	Motor Vehicle in Pavement Traffic	On (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
201601346821																				
2/3/2016 1:25 PM	Clear	Dry	0	0	0	0	Sideswipe Same Direction	Daylight	0.00	2436673.2129049 1139250.69879255	Pickup	Northeast	Changing Lanes	Motor Vehicle in Pavement Traffic	On (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
											SUV	North	Straight Ahead	Motor Vehicle in Pavement Traffic	On (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
201601343735																				
2/3/2016 4:02 PM	Clear	Dry	0	1	0	0	Turning	Daylight	0.00	2436673.36459208 1139298.36153162	Passenger	East	Turning Left	Motor Vehicle in Pavement Traffic	On (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
											Passenger	North	Straight Ahead	Motor Vehicle in Pavement Traffic	On (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
201601360172																				
3/16/2016 2:40 PM	Clear	Dry	0	0	0	0	Turning	Daylight	0.00	2436672.81821834 1139298.35304309	Passenger	North	Turning Left	Motor Vehicle in Pavement Traffic	On (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
											Passenger	North	Unknown	Motor Vehicle in Pavement Traffic	On (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
201601370570																				
4/2/2016 2:26 PM	Severe Cross Wind	Wet	0	0	0	0	Angle	Daylight	0.00	2436672.86618043 1139298.35378824	Van/Mini-Van	North	Straight Ahead	Motor Vehicle in Pavement Traffic	Intersection	(UNK)	(UNK)	(UNK)	(UNK)	1
											Pickup	East	Straight Ahead	Motor Vehicle in Pavement Traffic	Intersection	(UNK)	(UNK)	(UNK)	(UNK)	2



Coordinate Collision Diagram Report

1/1/2016 to 12/31/2016

For XCoordinate 2436672.81821834 : YCoordinate 1139298.35304309 | Foot Tolerance : 250 | County : Sangamon | Intersection Related: Intersections | *See Notes at End of Report.

Date	Weather	Roadway	A	Injuries B	C	Killed	Type of Crash	Light Condition	Mile	XCoordinate YCoordinate	Vehicle Type	DIRP	Maneuver	Event 1	Loc 1	Event 2	Loc 2	Event 3	Loc 3	Unit
201601384241																				
4/22/2016 11:43 PM	Clear	Dry	0	0	0	0	Turning	Daylight	0.00	2436672.81821834 1139298.35304309	Pickup	East	Turning Left	Motor Vehicle in n Traffic	Interseccio	(UNK)	(UNK)	(UNK)	(UNK)	1
											Passenger	West	Straight Ahead	Motor Vehicle in n Traffic	Interseccio	(UNK)	(UNK)	(UNK)	(UNK)	2
201601387307																				
5/1/2016 6:09 PM	Rain	Wet	0	0	0	0	Turning	Daylight	0.00	2436672.85616604 1139298.35521734	Passenger	North	Turning Left	Motor Vehicle in n Traffic	Interseccio	(UNK)	(UNK)	(UNK)	(UNK)	1
											Passenger	South	Straight Ahead	Motor Vehicle in n Traffic	Interseccio	(UNK)	(UNK)	(UNK)	(UNK)	2
201601387389																				
5/10/2016 12:39 PM	Cloudy/Overca st	Dry	0	0	0	0	Turning	Daylight	0.00	2436673.02249211 1139298.35621671	Pickup	Southeast	Turning Left	Motor Vehicle in n Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
											Passenger	North	Straight Ahead	Motor Vehicle in n Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
201601394461																				
5/18/2016 6:25 PM	Clear	Dry	0	0	1	0	Turning	Daylight	0.00	2436673.1189949 1139298.35771599	SUV	Northeast	Turning Left	Motor Vehicle in n Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
											Passenger	West	Straight Ahead	Motor Vehicle in n Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
201601388003																				
5/18/2016 7:27 PM	Clear	Dry	0	1	0	0	Turning	Daylight	0.00	2436672.81821834 1139298.35304309	Passenger	East	Turning Left	Motor Vehicle in n Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
											Passenger	North	Straight Ahead	Motor Vehicle in n Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2



Coordinate Collision Diagram Report

1/1/2016 to 12/31/2016

For XCoordinate 2436672.81821834 : YCoordinate 1139298.35304309 | Foot Tolerance : 250 | County : Sangamon | Intersection Related: Intersections | *See Notes at End of Report.

Date	Weather	Roadway	Injuries A B C	Killed	Type of Crash	Light Condition	Mile	XCoordinate YCoordinate	Vehicle Type	DIRP	Maneuver	Event 1	Loc 1	Event 2	Loc 2	Event 3	Loc 3	Unit
201601391122																		
5/27/2016 9:57 AM	Rain	Wet	0	1	1	0	Angle	Daylight	0.00	2436672.81821834 1139298.35304309	Passenger	East	Slow/Stop Vehicle in Traffic	Motor Vehicle in Pavement Traffic (Roadway)	(UNK)	(UNK)	(UNK)	1
201601463588																		
5/30/2016 4:20 PM	Clear	Wet	0	1	0	0	Fixed Object	Daylight	0.00	2436672.99358274 1139298.35576758	Passenger	West	Skidding/Control Loss	Other Fixed Object (Roadway)	(UNK)	(UNK)	(UNK)	1
201601407419																		
6/15/2016 3:09 PM	Clear	Dry	0	0	0	0	Turning	Daylight	0.00	2436672.81821834 1139298.35304309	Passenger	West	Turning Left	Motor Vehicle in n Traffic	(UNK)	(UNK)	(UNK)	1
201601406481																		
6/15/2016 5:17 PM	Clear	Dry	0	1	0	0	Front to Rear	Daylight	0.00	2436672.69677419 1139308.1135081	Passenger	South	Straight Ahead	Motor Vehicle in Pavement Traffic (Roadway)	(UNK)	(UNK)	(UNK)	1
201601428736																		
6/30/2016 9:36 AM	Clear	Dry	0	0	0	0	Turning	Daylight	0.00	2436672.98898174 1139298.35569609	Passenger	West	Turning Right	Motor Vehicle in Pavement Traffic (Roadway)	(UNK)	(UNK)	(UNK)	1
201601428736																		
7/14/2016 2:18 PM	Clear	Dry	0	0	1	0	Front to Rear	Daylight	0.00	2436673.1316676 1139298.35791288	Passenger	North	Straight Ahead	Motor Vehicle in Pavement Traffic (Roadway)	(UNK)	(UNK)	(UNK)	2
201601428736																		
7/14/2016 2:18 PM	Clear	Dry	0	0	1	0	Front to Rear	Daylight	0.00	2436673.1316676 1139298.35791288	Pickup	West	Straight Ahead	Motor Vehicle in n Traffic	(UNK)	(UNK)	(UNK)	1



Coordinate Collision Diagram Report

1/1/2016 to 12/31/2016

For XCoordinate 2436672.81821834 : YCoordinate 1139298.35304309 | Foot Tolerance : 250 | County : Sangamon | Intersection Related: Intersections | *See Notes at End of Report.

Date	Weather	Roadway	Injuries			Killed	Type of Crash	Light Condition	Mile	XCoordinate	Vehicle Type	DIRP	Maneuver	Event 1	Loc 1	Event 2	Loc 2	Event 3	Loc 3	Unit
			A	B	C															
201601437882											Pickup	West	Slow/Stop In Traffic	Motor Vehicle In Traffic	Interseccio	(UNK)	(UNK)	(UNK)	(UNK)	2
8/1/2016 4:19 PM	Clear	Dry	0	0	0	0	Front to Rear	Daylight	0.00	2436672.92415985 1139298.35469901	Passenger	South	Slow/Stop In Traffic	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
											Passenger	South	Slow/Stop In Traffic	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
201601463685																				
9/1/2016 11:19 AM	Clear	Dry	0	0	0	0	Front to Rear	Daylight	0.00	2436671.32091641 1139418.69118741	Pickup	South	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
											Passenger	South	Slow/Stop In Traffic	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
201601484857																				
11/1/2016 12:20 PM	Clear	Dry	0	0	0	0	Front to Rear	Daylight	0.00	2436672.81821834 1139298.35304309	SUV	East	Straight Ahead	Motor Vehicle In Traffic	Interseccio	(UNK)	(UNK)	(UNK)	(UNK)	1
											Passenger	East	Slow/Stop In Traffic	Motor Vehicle In Traffic	Interseccio	(UNK)	(UNK)	(UNK)	(UNK)	2
201601489819																				
11/21/2016 12:15 PM	Clear	Dry	0	0	0	0	Front to Rear	Daylight	0.00	2436672.8868808 1139298.35410984	Passenger	South	Straight Ahead	Motor Vehicle In Traffic	Interseccio	(UNK)	(UNK)	(UNK)	(UNK)	1
											Pickup	South	Slow/Stop - Left Turn	Motor Vehicle In Traffic	Interseccio	Motor Vehicle In Traffic	(UNK)	(UNK)	(UNK)	2
											SUV	South	Slow/Stop In Traffic	Motor Vehicle In Traffic	Interseccio	(UNK)	(UNK)	(UNK)	(UNK)	3
201601499177																				
12/16/2016 3:50 PM	Sleet/Hail	Ice	1	0	0	0	Front to Rear	Daylight	0.00	2436672.81821834 1139298.35304309	Passenger	East	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1



Coordinate Collision Diagram Report

1/1/2016 to 12/31/2016

For XCoordinate 2436672.81821834 : YCoordinate 1139298.35304309 | Foot Tolerance : 250 | County : Sangamon | Intersection Related: Intersections | *See Notes at End of Report.

Date	Weather	Roadway	Injuries A B C	Killed	Type of Crash	Light Condition	Mile	XCoordinate	Vehicle Type	DIRP	Maneuver	Event 1	Loc 1	Event 2	Loc 2	Event 3	Loc 3	Unit
									Van/Mini- Van	East	Slow/Stop In Traffic	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2



Coordinate Collision Diagram Report

1/1/2016 to 12/31/2016

For XCoordinate 2436672.81821834 : YCoordinate 1139298.35304309 | Foot Tolerance : 250 | County : Sangamon | Intersection Related: Intersections | *See Notes at End of Report.

TOTAL CRASHES	FATAL CRASHES	A INJURY CRASHES	B INJURY CRASHES	C INJURY CRASHES	PROPERTY DAMAGE CRASHES	TOTAL KILLED	TOTAL INJURED	A INJURIES	B INJURIES	C INJURIES
21	0	1	5	2	13	0	9	1	5	3

Type of Crash	Total	%	Day of Wk	Total	%	Hour of Day	Total	%	Vehicle Type	Total	%
Angle	2	9.5%	Monday	3	14.3%	09 AM	2	9.5%	Passenger	26	61.9%
Fixed Object	1	4.8%	Tuesday	2	9.5%	11 AM	1	4.8%	Pickup	10	23.8%
Front to Rear	7	33.3%	Wednesday	7	33.3%	Noon	3	14.3%	SUV	4	9.5%
Slideshow Same Direction	1	4.8%	Thursday	3	14.3%	1 PM	1	4.8%	Van/Mini-Van	2	4.8%
Turning	10	47.6%	Friday	4	19.0%	2 PM	3	14.3%	TOTAL:	42	
TOTAL:	21		Saturday	1	4.8%	3 PM	2	9.5%			
			Sunday	1	4.8%	4 PM	3	14.3%			
			TOTAL:	21		5 PM	2	9.5%			
						6 PM	2	9.5%			
						7 PM	1	4.8%			
						11 PM	1	4.8%			
						TOTAL:	21				

Weather Cond	Total	%	Light Cond	Total	%	Road Surface	Total	%	DIRP	Total	%
Clear	15	71.4%	Daylight	20	95.2%	Dry	16	76.2%	East	10	23.8%
Cloudy/Overcast	1	4.8%	Dusk	1	4.8%	Ice	1	4.8%	North	10	23.8%
Rain	3	14.3%	TOTAL:	21		Wet	4	19.0%	Northeast	2	4.8%
Severe Cross Wind	1	4.8%				TOTAL:	21		South	12	28.6%
									Southeast	1	2.4%



Coordinate Collision Diagram Report

1/1/2016 to 12/31/2016

For XCoordinate 2436672.81821834 : YCoordinate 11392298.35304309 | Foot Tolerance : 250 | County : Sangamon | Intersection Related: Intersections | *See Notes at End of Report.

Weather Cond	Total	%	D/RP	Total	%
Sleet/Hail	1	4.8%	West	7	16.7%
TOTAL:	21		TOTAL:	42	



Coordinate Collision Diagram Report

1/1/2016 to 12/31/2016

For XCoordinate 2436672.81821834 : YCoordinate 1139298.35304309 | Foot Tolerance : 250 | County : Sangamon | Intersection Related: Intersections | *See Notes at End of Report.

Notes

DISCLAIMER: The motor vehicle crash data referenced herein was provided by the Illinois Department of Transportation. Any conclusions drawn from analysis of the aforementioned data are the sole responsibility of the data recipient(s). Additionally, for coding years 2015 to present, the Bureau of Data Collection uses the exact latitude/longitude supplied by the investigating law enforcement agency to locate crashes. Therefore, location data may vary in previous years since data prior to 2015 was physically located by bureau personnel.



Coordinate Collision Diagram Report

1/1/2017 to 12/31/2017

For XCoordinate 2436672.81821834 : YCoordinate 1139298.35304309 | Foot Tolerance : 250 | County : Sangamon | Intersection Related: Intersections | *See Notes at End of Report.

Date	Weather	Roadway	Injuries			Killed	Type of Crash	Light Condition	Mile	XCoordinate YCoordinate	Vehicle Type	DIRP	Maneuver	Event 1 Loc 1	Event 2 Loc 2	Event 3 Loc 3	Unit	
			A	B	C													
201701366176																		
1/12/2017 9:04 AM	Clear	Dry	0	0	0	0	Turning	Daylight	0.00	2436672.82446812 1139297.93216479	Passenger	North	Turning Left	Motor On Vehicle In Pavement Traffic (Roadway)	(UNK)	(UNK)	(UNK)	1
											Passenger	South	Straight Ahead	Motor On Vehicle In Pavement Traffic (Roadway)	(UNK)	(UNK)	(UNK)	2
201701374831																		
2/6/2017 8:32 AM	Clear	Dry	0	0	0	0	Turning	Daylight	0.00	2436672.82370678 1139297.98343573	Passenger	East	Turning Left	Motor On Vehicle In Pavement Traffic (Roadway)	(UNK)	(UNK)	(UNK)	1
											Passenger	North	Straight Ahead	Motor On Vehicle In Pavement Traffic (Roadway)	(UNK)	(UNK)	(UNK)	2
201701376196																		
2/14/2017 9:50 AM	Cloudy/Overcast	Dry	0	0	0	0	Front to Rear	Daylight	0.00	2436672.81821834 1139298.35304309	Passenger	North	Straight Ahead	Motor On Vehicle In Pavement Traffic (Roadway)	(UNK)	(UNK)	(UNK)	1
											Van/Mini-Van	North	Slow/Stop In Traffic	Motor On Vehicle In Pavement Traffic (Roadway)	(UNK)	(UNK)	(UNK)	2
201701387875																		
3/14/2017 8:10 AM	Snow	Wet	0	0	0	0	Turning	Daylight	0.00	2436672.81821834 1139298.35304309	Passenger	East	Turning Left	Motor On Vehicle In Pavement Traffic (Roadway)	(UNK)	(UNK)	(UNK)	1
											Passenger	North	Straight Ahead	Motor On Vehicle In Pavement Traffic (Roadway)	(UNK)	(UNK)	(UNK)	2
201701389984																		
3/18/2017 8:17 PM	Clear	Dry	0	2	0	0	Angle	Darkness	0.00	2436672.81821834 1139298.35304309	Passenger	South	Straight Ahead	Motor On Vehicle In Pavement Traffic (Roadway)	(UNK)	(UNK)	(UNK)	1
											Passenger	East	Straight Ahead	Motor On Vehicle In Pavement Traffic (Roadway)	(UNK)	(UNK)	(UNK)	2



1/1/2017 to 12/31/2017

For XCordinate 2436672.81821834 : YCoordinate 1139298.35304309 | Foot Tolerance : 250 | County : Sangamon | Intersection Related: Intersections | *See Notes at End of Report.

Date	Weather	Roadway	Injuries			Killed	Type of Crash	Light Condition	Mile	XCoordinate YCoordinate	Vehicle Type	DIRP	Maneuver	Event 1	Loc 1	Event 2	Loc 2	Event 3	Loc 3	Unit
			A	B	C															
201701390871	Clear	Dry	0	0	0	0	Turning	Daylight	0.00	2436672.82349641 1139297.99760295	Passenger Vehicle	West	Turning Left	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
3/28/2017 3:30 PM	Clear	Dry	0	0	0	0	Turning	Daylight	0.00	2436672.82349641 1139297.99760295	Passenger Vehicle	West	Turning Left	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
201701404625	Clear	Dry	0	0	3	0	Angle	Daylight	0.00	2436672.83088291 1139297.50017524	Passenger Vehicle	North	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
4/4/2017 6:25 PM	Clear	Dry	0	0	3	0	Angle	Daylight	0.00	2436672.83088291 1139297.50017524	Passenger Vehicle	North	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
201701404760	Clear	Dry	0	0	0	0	Sideswipe Same Direction	Daylight	0.00	2436672.81821834 1139298.35304309	Passenger Vehicle	West	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
4/6/2017 7:26 AM	Clear	Dry	0	0	0	0	Sideswipe Same Direction	Daylight	0.00	2436672.81821834 1139298.35304309	Passenger Vehicle	West	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
201701424080	Clear	Dry	0	2	0	0	Turning	Daylight	0.00	2436672.81821834 1139298.35304309	SUV	Southwest	Turning Left	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
5/26/2017 4:18 PM	Clear	Dry	0	2	0	0	Turning	Daylight	0.00	2436672.81821834 1139298.35304309	SUV	Southwest	Turning Left	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1



Coordinate Collision Diagram Report

1/1/2017 to 12/31/2017

For XCoordinate 2436672.81821834 ; YCoordinate 1139298.35304309 | Foot Tolerance : 250 | County : Sangamon | Intersection Related: Intersections | *See Notes at End of Report.

Date	Weather	Roadway	A	Injuries B	C	Killed	Type of Crash	Light Condition	Mile	XCoordinate	YCoordinate	Vehicle Type	DIRP	Maneuver	Event 1	Loc 1	Event 2	Loc 2	Event 3	Loc 3	Unit
201701426537												Passenger	East	Straight Ahead	Motor Vehicle in Traffic	Intersection	(UNK)	(UNK)	(UNK)	(UNK)	2
6/2/2017 8:30 AM	Clear	Dry	0	0	0	0	Turning	Daylight	0.00	2436672.81821834	1139298.35304309	Passenger	South	Turning Left	Motor Vehicle in Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
201701432513												Passenger	North	Straight Ahead	Motor Vehicle in Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
6/14/2017 11:00 AM	Clear	Dry	0	0	0	0	Turning	Daylight	0.00	2436672.81821834	1139298.35304309	Passenger	South	Turning Left	Motor Vehicle in Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
201701435050												Passenger	North	Straight Ahead	Motor Vehicle in Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
6/20/2017 10:50 AM	Clear	Dry	0	0	0	0	Front to Rear	Daylight	0.00	2436672.81821834	1139298.35304309	Other	North	Straight Ahead	Motor Vehicle in Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
201701437930												Passenger	North	Slow/Stop - Left Turn	Motor Vehicle in Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
6/28/2017 4:12 PM	Clear	Dry	0	0	0	0	Front to Rear	Daylight	0.00	2436672.81821834	1139298.35304309	Unknown	East	Unknown	Motor Vehicle in Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
201701443968												Passenger	East	Straight Ahead	Motor Vehicle in Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
7/16/2017 6:24 PM	Clear	Wet	0	0	1	0	Angle	Daylight	0.00	2436672.82279618	1139298.0447582	Passenger	West	Straight Ahead	Motor Vehicle in Traffic	Intersection	(UNK)	(UNK)	(UNK)	(UNK)	1
												SUV	South	Straight Ahead	Motor Vehicle in Traffic	Intersection	(UNK)	(UNK)	(UNK)	(UNK)	2



Coordinate Collision Diagram Report

1/1/2017 to 12/31/2017

For XCoordinate 2436672.81821834 : YCoordinate 1139298.35304309 | Foot Tolerance : 250 | County : Sangamon | Intersection Related: Intersections | *See Notes at End of Report.

Date	Weather	Roadway	Injuries			Killed	Type of Crash	Light Condition	Mile	XCoordinate YCoordinate	Vehicle Type	DIRP	Maneuver	Event 1	Loc 1	Event 2	Loc 2	Event 3	Loc 3	Unit
201701452472																				
8/12/2017 3:22 PM	Clear	Dry	0	0	0	0	Front to Rear	Daylight	0.00	2436672.81821834 1139298.35304309	Passenger	North	Straight Ahead	Motor Vehicle in n Traffic	Interseccio (UNK)	(UNK)	(UNK)	(UNK)	(UNK)	1
201701452728																				
8/13/2017 6:23 PM	Clear	Dry	1	0	0	0	Turning	Daylight	0.00	2436672.81821834 1139298.35304309	Passenger	North	Turning Left	Motor Vehicle In Pavement Traffic	On (UNK)	(UNK)	(UNK)	(UNK)	(UNK)	1
201701453227																				
8/15/2017 8:25 AM	Cloudy/Overcast	Dry	0	0	0	0	Front to Rear	Daylight	0.00	2436672.81821834 1139298.35304309	Motor Driven Cycle	South	Straight Ahead	Motor Vehicle In Pavement Traffic	On (UNK)	(UNK)	(UNK)	(UNK)	(UNK)	2
201701457332																				
8/29/2017 8:12 PM	Clear	Dry	0	0	0	0	Front to Rear	Darkness, Lighted Road	0.00	2436672.81821834 1139298.35304309	Passenger	South	Straight Ahead	Motor Vehicle In Pavement Traffic	On (UNK)	(UNK)	(UNK)	(UNK)	(UNK)	1
201701458320																				
9/1/2017 9:22 PM	Clear	Dry	0	0	0	0	Front to Rear	Darkness, Lighted Road	0.00	2436672.81821834 1139298.35304309	Passenger	East	Straight Ahead	Motor Vehicle In Pavement Traffic	On (UNK)	(UNK)	(UNK)	(UNK)	(UNK)	2
201701458320																				
9/1/2017 9:22 PM	Clear	Dry	0	0	0	0	Front to Rear	Darkness, Lighted Road	0.00	2436672.81821834 1139298.35304309	Pickup	North	Straight Ahead	Motor Vehicle in n Traffic	Interseccio (UNK)	(UNK)	(UNK)	(UNK)	(UNK)	1
201701458320																				
9/1/2017 9:22 PM	Clear	Dry	0	0	0	0	Front to Rear	Darkness, Lighted Road	0.00	2436672.81821834 1139298.35304309	Pickup	North	Slow/Stop - Left Turn	Motor Vehicle in n Traffic	Interseccio (UNK)	(UNK)	(UNK)	(UNK)	(UNK)	2



Coordinate Collision Diagram Report

1/1/2017 to 12/31/2017

For XCoordinate 2436672.81821834 : YCoordinate 1139298.35304309 | Foot Tolerance : 250 | County : Sangamon | Intersection Related: Intersections | *See Notes at End of Report.

Date	Weather	Roadway	Injures A B C	Killed	Type of Crash	Light Condition	Mile	XCoordinate YCoordinate	Vehicle Type	DIRP	Maneuver	Event 1	Loc 1	Event 2	Loc 2	Event 3	Loc 3	Unit
201701460291																		
9/9/2017 11:42 AM	Clear	Dry	0	0	0	Angle	Daylight	0.00	2436672.81821834 1139298.35304309	Passenger	East	Straight Ahead	Motor Vehicle in n Traffic	Intersectio	(UNK)	(UNK)	(UNK)	1
										SUV	South	Straight Ahead	Motor Vehicle in n Traffic	Intersectio	(UNK)	(UNK)	(UNK)	2
201701467416																		
10/6/2017 11:37 AM	Rain	Wet	0	0	0	Front to Rear	Daylight	0.00	2436672.81821834 1139298.35304309	Passenger	East	Straight Ahead	Motor Vehicle in Pavement Traffic	On (Roadway)	(UNK)	(UNK)	(UNK)	1
										Pickup	East	Slow/Stop In Traffic	Motor Vehicle in Pavement Traffic	On (Roadway)	(UNK)	(UNK)	(UNK)	2
201701470995																		
10/19/2017 8:19 AM	Clear	Dry	0	0	2	Turning	Daylight	0.00	2436672.81852257 1139298.33255506	Passenger	Northwest	Turning Left	Motor Vehicle in Pavement Traffic	On (Roadway)	(UNK)	(UNK)	(UNK)	1
										Passenger	South	Straight Ahead	Motor Vehicle in Pavement Traffic	On (Roadway)	(UNK)	(UNK)	(UNK)	2
201701472021																		
10/23/2017 3:33 PM	Clear	Dry	0	0	0	Turning	Daylight	0.00	2436672.81989094 1139298.24040545	Passenger	South	Turning Left	Motor Vehicle in Pavement Traffic	On (Roadway)	(UNK)	(UNK)	(UNK)	1
										Pickup	North	Straight Ahead	Motor Vehicle in Pavement Traffic	On (Roadway)	(UNK)	(UNK)	(UNK)	2
201701483482																		
12/9/2017 11:36 PM	Clear	Dry	2	0	0	Turning	Daylight	0.00	2436672.81821834 1139298.35304309	SUV	East	Turning Left	Motor Vehicle in Pavement Traffic	On (Roadway)	(UNK)	(UNK)	(UNK)	1
										Passenger	West	Straight Ahead	Motor Vehicle in Pavement Traffic	On (Roadway)	(UNK)	(UNK)	(UNK)	2



Coordinate Collision Diagram Report

1/1/2017 to 12/31/2017

For XCoordinate 2436672.81821834 : YCoordinate 1139298.35304309 | Foot Tolerance : 250 | County : Sangamon | Intersection Related: Intersections | *See Notes at End of Report.

Date	Weather	Roadway	----- A	Injures B	----- C	Killed	Type of Crash	Light Condition	Mile	XCoordinate YCoordinate	Vehicle Type	DIRP	Maneuver	Event 1	Loc 1	Event 2	Loc 2	Event 3	Loc 3	Unit
201701484978																				
12/15/2017 1:01 PM	Clear	Dry	1	0	0	0	Turning	Daylight	0.00	2436672.81821834 1139298.35304309	Passenger	Southeast	Turning Left	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
											Passenger	North	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2

201701473736																				
10/30/2017 7:33 AM	Rain	Wet	0	0	1	0	Front to Rear	Daylight	2.12	2436642.76289006 1139297.78501315	SUV	East	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
											Passenger	East	Slow/Stop In Traffic	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2



Coordinate Collision Diagram Report

1/1/2017 to 12/31/2017

For XCoordinate 2436672.81821834 : YCoordinate 1139298.35304309 | Foot Tolerance : 250 | County : Sangamon | Intersection Related: Intersections | *See Notes at End of Report.

TOTAL CRASHES	FATAL CRASHES	A INJURY CRASHES	B INJURY CRASHES	C INJURY CRASHES	PROPERTY DAMAGE CRASHES	TOTAL KILLED	TOTAL INJURED	A INJURIES	B INJURIES	C INJURIES
27	0	3	2	4	18	0	15	4	4	7

Type of Crash	Total	%	Day of Wk	Total	%	Hour of Day	Total	%	Vehicle Type	Total	%
Angle	4	14.8%	Monday	3	11.1%	07 AM	2	7.4%	Motor Driven Cycle	1	1.8%
Front to Rear	9	33.3%	Tuesday	8	29.6%	08 AM	5	18.5%	Other	1	1.8%
Slidewipe Same Direction	1	3.7%	Wednesday	2	7.4%	09 AM	2	7.4%	Passenger	40	71.4%
Turning	13	48.1%	Thursday	3	11.1%	10 AM	1	3.7%	Pickup	4	7.1%
TOTAL:	27		Friday	5	18.5%	11 AM	4	14.8%	SUV	8	14.3%
			Saturday	4	14.8%	1 PM	1	3.7%	Unknown	1	1.8%
			Sunday	2	7.4%	3 PM	3	11.1%	Van/Min-Van	1	1.8%
			TOTAL:	27		4 PM	2	7.4%	TOTAL:	56	
						6 PM	3	11.1%			
						8 PM	2	7.4%			
						9 PM	1	3.7%			
						11 PM	1	3.7%			
						TOTAL:	27				
Weather Cond	Total	%	Light Cond	Total	%	Road Surface	Total	%	DIRP	Total	%
Clear	22	81.5%	Darkness	1	3.7%	Dry	23	85.2%	East	18	32.1%
Cloudy/Overcast	2	7.4%	Darkness, Lighted Road	2	7.4%	Wet	4	14.8%	North	17	30.4%
Rain	2	7.4%	Daylight	24	88.9%	TOTAL:	27		Northwest	1	1.8%
			TOTAL:	27					South	12	21.4%



Coordinate Collision Diagram Report

1/1/2017 to 12/31/2017

For XCoordinate 2436672.81821834 : YCoordinate 1139298.35304309 | Foot Tolerance : 250 | County : Sangamon | Intersection Related: Intersections | *See Notes at End of Report.

Weather Cond	Total	%
Snow	1	3.7%
TOTAL:	27	

DIRP	Total	%
Southeast	1	1.8%
Southwest	1	1.8%
West	6	10.7%
TOTAL:	56	



Coordinate Collision Diagram Report

1/1/2017 to 12/31/2017

For XCoordinate 2436672.81821834 : YCoordinate 1139298.35304309 | Foot Tolerance : 250 | County : Sangamon | Intersection Related: Intersections | *See Notes at End of Report.

Notes

DISCLAIMER: The motor vehicle crash data referenced herein was provided by the Illinois Department of Transportation. Any conclusions drawn from analysis of the aforementioned data are the sole responsibility of the data recipient(s). Additionally, for coding years 2015 to present, the Bureau of Data Collection uses the exact latitude/longitude supplied by the investigating law enforcement agency to locate crashes. Therefore, location data may vary in previous years since data prior to 2015 was physically located by bureau personnel.



Coordinate Collision Diagram Report

1/1/2018 to 12/31/2018

For XCoordinate 2436672.81821834 : YCoordinate 1139298.35304309 | Foot Tolerance : 250 | County : Sangamon | Intersection Related: Intersections | *See Notes at End of Report.

Date	Weather	Roadway	----- A	Injures B	----- C	Killed	Type of Crash	Light Condition	Mile	XCoordinate YCoordinate	Vehicle Type	DIRP	Maneuver	Event 1	Loc 1	Event 2	Loc 2	Event 3	Loc 3	Unit
201801411014																				
1/10/2018 8:52 AM	Cloudy/Overca st	Wet	0	1	0	0	Angle	Daylight	0.00	2436672.81821834 1139298.35304309	Passenger	West	Straight Ahead	Motor Vehicle in Pavement Traffic (Roadway)	On	(UNK)	(UNK)	(UNK)	(UNK)	1
201801413067																				
1/17/2018 5:01 PM	Clear	Dry	0	0	1	0	Turning	Daylight	0.00	2436672.82067322 1139298.18772458	SUV	East	Turning Left	Motor Vehicle in Pavement Traffic (Roadway)	On	(UNK)	(UNK)	(UNK)	(UNK)	1
201801419481																				
2/9/2018 7:58 AM	Clear	Dry	0	0	0	0	Turning	Daylight	0.00	2436672.81821834 1139298.35304309	Passenger	East	Turning Left	Motor Vehicle in Pavement Traffic (Roadway)	On	(UNK)	(UNK)	(UNK)	(UNK)	1
201801420331																				
2/19/2018 12:09 PM	Clear	Dry	0	0	0	0	Front to Rear	Daylight	0.00	2436672.81934066 1139298.2774627	SUV	West	Straight Ahead	Motor Vehicle in Pavement Traffic (Roadway)	On	(UNK)	(UNK)	(UNK)	(UNK)	2
201801422177																				
2/19/2018 1:06 PM	Cloudy/Overca st	Wet	0	0	0	0	Angle	Daylight	0.00	2436672.81980578 1139298.24614038	Passenger	East	Straight Ahead	Motor Vehicle in Pavement Traffic (Roadway)	On	(UNK)	(UNK)	(UNK)	(UNK)	1



Coordinate Collision Diagram Report

1/1/2018 to 12/31/2018

For XCoordinate 2436672.81821834 : YCoordinate 1139298.35304309 | Foot Tolerance : 250 | County : Sangamon | Intersection Related: Intersections | *See Notes at End of Report.

Date	Weather	Roadway	Injuries A B C	Killed	Type of Crash	Light Condition	Mile	XCoordinate YCoordinate	Vehicle Type	DIRP	Maneuver	Event 1	Loc 1	Event 2	Loc 2	Event 3	Loc 3	Unit
201801423384									Passenger	South	Slow/Stop In Traffic	Motor Vehicle In n Traffic	Intersectio (UNK)	(UNK)	(UNK)	(UNK)	(UNK)	2
3/23/2018 12:47 PM	Clear	Dry	0	0	0	Turning	Daylight	0.00 2436672.81821834 1139298.35304309	Passenger	Southeast	Turning Left	Motor Vehicle In Pavement Traffic (Roadway)	On (UNK)	(UNK)	(UNK)	(UNK)	(UNK)	1
									Passenger	North	Straight Ahead	Motor Vehicle In Pavement Traffic (Roadway)	On (UNK)	(UNK)	(UNK)	(UNK)	(UNK)	2
201801423535																		
3/26/2018 8:05 PM	Rain	Wet	0	0	1	Pedestrian	Darkness, Lighted Road	0.00 2436672.81821834 1139298.35304309	SUV	West	Turning Left	Pedestria n (Roadway)	On (UNK)	(UNK)	(UNK)	(UNK)	(UNK)	1
201801206830																		
3/28/2018 7:20 AM	Cloudy/Overca st	Dry	0	1	0	Turning	Daylight	0.00 2436672.81821834 1139298.35304309	Passenger	North	Turning Left	Motor Vehicle In Pavement Traffic (Roadway)	On (UNK)	(UNK)	(UNK)	(UNK)	(UNK)	1
									Passenger	South	Straight Ahead	Motor Vehicle In Pavement Traffic (Roadway)	On (UNK)	(UNK)	(UNK)	(UNK)	(UNK)	2
201801432496																		
4/9/2018 11:19 AM	Cloudy/Overca st	Wet	0	0	1	Angle	Daylight	0.00 2436672.82076266 1139298.18170128	Pickup	South	Straight Ahead	Motor Vehicle In n Traffic	Intersectio (UNK)	(UNK)	(UNK)	(UNK)	(UNK)	1
									Passenger	West	Straight Ahead	Motor Vehicle In n Traffic	Intersectio (UNK)	(UNK)	(UNK)	(UNK)	(UNK)	2
									Passenger	West	Straight Ahead	Motor Vehicle In Pavement Traffic (Roadway)	On (UNK)	(UNK)	(UNK)	(UNK)	(UNK)	3
201801432606																		
4/25/2018 9:01 AM	Clear	Dry	0	1	1	0	Front to Rear	Daylight	0.00 2436687.40824489 1139298.5797154	Passenger	West	Straight Ahead	Motor Vehicle In Pavement Traffic (Roadway)	On (UNK)	(UNK)	(UNK)	(UNK)	1
									Passenger	West	Slow/Stop In Traffic	Motor Vehicle In Pavement Traffic (Roadway)	On (UNK)	(UNK)	(UNK)	(UNK)	(UNK)	2



Coordinate Collision Diagram Report

1/1/2018 to 12/31/2018

For XCoordinate 2436672.81821834 : YCoordinate 1139298.35304309 | Foot Tolerance : 250 | County : Sangamon | Intersection Related: Intersections | *See Notes at End of Report.

Date	Weather	Roadway	Injures A B C	Killed	Type of Crash	Light Condition	Mile	XCoordinate YCoordinate	Vehicle Type	DIRP	Maneuver	Event 1	Loc 1	Event 2	Loc 2	Event 3	Loc 3	Unit
201801440359																		
5/12/2018 10:50 AM	Clear	Dry	0	0	0	0	0.00	2436672.81821834 1139298.35304309	Passenger	South	Straight Ahead	Motor Vehicle On Pavement Traffic (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	(UNK)	1
									Passenger	South	Slow/Stop In Traffic	Motor Vehicle On Pavement Traffic (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	(UNK)	2
									Van/Mini-Van	South	Slow/Stop In Traffic	Motor Vehicle On Pavement Traffic (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	(UNK)	3
201801444283																		
5/30/2018 7:57 AM	Clear	Wet	0	0	0	0	0.00	2436672.81821834 1139298.35304309	Passenger	North	Turning Left	Motor Vehicle On Pavement Traffic (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	(UNK)	1
									Passenger	South	Straight Ahead	Motor Vehicle On Pavement Traffic (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	(UNK)	2
201801448251																		
6/16/2018 11:43 AM	Clear	Dry	0	0	0	0	0.00	2436672.81963459 1139298.25768856	Passenger	Southeast	Turning Left	Motor Vehicle On Pavement Traffic (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	(UNK)	1
									Passenger	North	Straight Ahead	Motor Vehicle On Pavement Traffic (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	(UNK)	2
201801448544																		
6/17/2018 5:15 PM	Clear	Wet	0	1	0	0	0.00	2436672.81821834 1139298.35304309	Passenger	Southeast	Turning Left	Motor Vehicle In n Traffic	(UNK)	(UNK)	(UNK)	(UNK)	(UNK)	1
									Passenger	North	Straight Ahead	Motor Vehicle In n Traffic	(UNK)	(UNK)	(UNK)	(UNK)	(UNK)	2
201801485183																		
6/18/2018 4:25 PM	Clear	Dry	0	0	0	0	0.00	2436672.81821834 1139298.35304309	Passenger	South	Straight Ahead	Motor Vehicle On Pavement Traffic (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	(UNK)	1
									Passenger	South	Slow/Stop In Traffic	Motor Vehicle On Pavement Traffic (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	(UNK)	2



Coordinate Collision Diagram Report

1/1/2018 to 12/31/2018

For XCoordinate 2436672.81821834 : YCoordinate 1139298.35304309 | Foot Tolerance : 250 | County : Sangamon | Intersection Related: Intersections | *See Notes at End of Report.

Date	Weather	Roadway	A	Injures B	C	Killed	Type of Crash	Light Condition	Mile	XCoordinate YCoordinate	Vehicle Type	DIRP	Maneuver	Event 1	Loc 1	Event 2	Loc 2	Event 3	Loc 3	Unit
201801452927																				
7/5/2018 6:28 PM	Rain	Wet	0	0	0	0	Fixed Object	Daylight	0.00	2436672.8955737 1139293.14371523	Passenger	West	Turning Left	Ran Off Roadway	Other Fixed Object					1
201801455931																				
8/2/2018 11:05 AM	Clear	Dry	0	0	1	0	Front to Rear	Daylight	0.00	2436672.81821834 1139298.35304309	Passenger	North	Straight Ahead	Motor Vehicle In Pavement Traffic (Roadway)	On (UNK)	(UNK)	(UNK)	(UNK)	(UNK)	1
201801455926																				
8/4/2018 9:53 AM	Clear	Dry	0	1	0	0	Front to Rear	Daylight	0.00	2436672.81821834 1139298.35304309	Passenger	West	Straight Ahead	Motor Vehicle In Pavement Traffic (Roadway)	On (UNK)	(UNK)	(UNK)	(UNK)	(UNK)	1
201801455791																				
8/6/2018 8:49 AM	Clear	Dry	0	0	0	0	Front to Rear	Daylight	0.00	2436672.81821834 1139298.35304309	SUV	West	Slow/Stop In Traffic	Motor Vehicle In Pavement Traffic (Roadway)	On (UNK)	(UNK)	(UNK)	(UNK)	(UNK)	2
201801465654																				
8/26/2018 9:17 AM	Clear	Dry	0	0	0	0	Turning	Daylight	0.00	2436672.81821834 1139298.35304309	Passenger	North	Straight Ahead	Motor Vehicle In Pavement Traffic (Roadway)	On (UNK)	(UNK)	(UNK)	(UNK)	(UNK)	1
201801465641																				
9/7/2018 5:27 PM	Rain	Dry	0	0	0	0	Turning	Daylight	0.00	2436672.81821834 1139298.35304309	Passenger	North	Straight Ahead	Motor Vehicle In Pavement Traffic (Roadway)	On (UNK)	(UNK)	(UNK)	(UNK)	(UNK)	1



Coordinate Collision Diagram Report

1/1/2018 to 12/31/2018

For XCoordinate 2436672.81821834 : YCoordinate 1139298.35304309 | Foot Tolerance : 250 | County : Sangamon | Intersection Related: Intersections | *See Notes at End of Report.

Date	Weather	Roadway	Injuries A B C	Killed	Type of Crash	Light Condition	Mile	XCoordinate YCoordinate	Vehicle Type	DIRP	Maneuver	Event 1	Loc 1	Event 2	Loc 2	Event 3	Loc 3	Unit
201801466694									Passenger	South	Turning Left	Motor Vehicle In Pavement Traffic (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	(UNK)	2
9/8/2018 12:20 PM	Clear	Wet	0	0	0	Turning	Daylight	0.00	2436672.81821834 1139298.35304309									
									Van/Mini-Van	North	Turning Left	Motor Vehicle In Pavement Traffic (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	(UNK)	1
									Passenger	West	Slow/Stop - Load/Unload	Motor Vehicle In Pavement Traffic (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	(UNK)	2
201801474769																		
10/8/2018 10:52 PM	Clear	Dry	0	0	0	Angle	Daylight	0.00	2436672.81821834 1139298.35304309									
									Passenger	South	Straight Ahead	Motor Vehicle In n Traffic	(UNK)	(UNK)	(UNK)	(UNK)	(UNK)	1
									Passenger	West	Straight Ahead	Motor Vehicle In n Traffic	(UNK)	(UNK)	(UNK)	(UNK)	(UNK)	2
201801482498																		
11/6/2018 5:24 PM	Clear	Dry	0	0	0	Turning	Darkness, Lighted Road	0.00	2436672.81821834 1139298.35304309									
									Passenger	North	Turning Left	Motor Vehicle In n Traffic	(UNK)	(UNK)	(UNK)	(UNK)	(UNK)	1
									Passenger	West	Straight Ahead	Motor Vehicle In n Traffic	(UNK)	(UNK)	(UNK)	(UNK)	(UNK)	2
201801483087																		
11/6/2018 9:30 PM	Snow	Snow or Slush	0	0	0	Front to Rear	Darkness, Lighted Road	0.00	2436672.81821834 1139298.35304309									
									Passenger	North	Straight Ahead	Motor Vehicle In Pavement Traffic (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	(UNK)	1
									Passenger	North	Slow/Stop In Traffic	Motor Vehicle In Pavement Traffic (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	(UNK)	2
201801489433																		
12/1/2018 4:45 AM	Rain	Wet	0	2	0	Angle	Darkness	0.00	2436672.81821834 1139298.35304309									
									Van/Mini-Van	South	Straight Ahead	Motor Vehicle In Pavement Traffic (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	(UNK)	1
									Van/Mini-Van	East	Unknown	Motor Vehicle In Pavement Traffic (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	(UNK)	2



Coordinate Collision Diagram Report

1/1/2018 to 12/31/2018

For XCoordinate 2436672.81821834 : YCoordinate 1139298.35304309 | Foot Tolerance : 250 | County : Sangamon | Intersection Related: Intersections | *See Notes at End of Report.

Date	Weather	Roadway	Injuries			Killed	Type of Crash	Light Condition	Mile	XCoordinate	YCoordinate	Vehicle Type	DIRP	Maneuver	Event 1	Loc 1	Event 2	Loc 2	Event 3	Loc 3	Unit
201801492761			A	B	C																
12/14/2018 6:02 PM	Clear	Dry	0	0	0	0	Turning	Darkness, Lighted Road	0.00	2436672.81821834	1139298.35304309	Farm Equipment	North	Straight Ahead	Motor Vehicle in Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
												Farm Equipment	East	Turning Left	Motor Vehicle in Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2



Coordinate Collision Diagram Report

1/1/2018 to 12/31/2018

For XCoordinate 2436672.81821834 : YCoordinate 1139298.35304309 | Foot Tolerance : .250 | County : Sangamon | Intersection Related: Intersections | *See Notes at End of Report.

TOTAL CRASHES	FATAL CRASHES	A INJURY CRASHES	B INJURY CRASHES	C INJURY CRASHES	PROPERTY DAMAGE CRASHES	TOTAL KILLED	TOTAL INJURED	A INJURIES	B INJURIES	C INJURIES
27	0	0	6	4	17	0	12	0	2	5

Type of Crash	Total	%	Day of Wk	Total	%	Hour of Day	Total	%	Vehicle Type	Total	%
Angle	5	18.5%	Monday	7	25.9%	04 AM	1	3.7%	Farm Equipment	2	3.6%
Fixed Object	1	3.7%	Tuesday	1	3.7%	07 AM	3	11.1%	Passenger	39	69.6%
Front to Rear	8	29.6%	Wednesday	5	18.5%	08 AM	2	7.4%	Pickup	1	1.8%
Pedestrian	1	3.7%	Thursday	3	11.1%	09 AM	3	11.1%	SUV	9	16.1%
Turning	12	44.4%	Friday	4	14.8%	10 AM	1	3.7%	Van/Mini-Van	5	8.9%
TOTAL:	27		Saturday	5	18.5%	11 AM	3	11.1%	TOTAL:	56	
			Sunday	2	7.4%	Noon	3	11.1%			
			TOTAL:	27		1 PM	1	3.7%			
						4 PM	1	3.7%			
						5 PM	4	14.8%			
						6 PM	2	7.4%			
						8 PM	1	3.7%			
						9 PM	1	3.7%			
						10 PM	1	3.7%			
						TOTAL:	27				
Weather Cond	Total	%	Light Cond	Total	%	Road Surface	Total	%	DIRP	Total	%
Clear	18	66.7%	Darkness	1	3.7%	Dry	17	63.0%	East	8	14.3%
Cloudy/Overcast	4	14.8%	Darkness, Lighted Road	4	14.8%	Snow or Slush	1	3.7%	North	18	32.1%



Coordinate Collision Diagram Report

1/1/2018 to 12/31/2018

For XCoordinate 2436672.81821834 : YCoordinate 1139298.35304309 | Foot Tolerance : 250 | County : Sangamon | Intersection Related: Intersections | *See Notes at End of Report.

Weather Cond	Total	%	Light Cond	Total	%	Road Surface	Total	%	DIRP	Total	%
Rain	4	14.8%	Daylight	22	81.5%	Wet	9	33.3%	South	12	21.4%
Snow	1	3.7%	TOTAL:	27		TOTAL:	27		Southeast	3	5.4%
TOTAL:	27								Unknown	1	1.8%
									West	14	25.0%
									TOTAL:	56	



Coordinate Collision Diagram Report

1/1/2018 to 12/31/2018

For XCoordinate 2436672.81821834 : YCoordinate 1139298.35304309 | Foot Tolerance : 250 | County : Sangamon | Intersection Related: Intersections | *See Notes at End of Report.

Notes

DISCLAIMER: The motor vehicle crash data referenced herein was provided by the Illinois Department of Transportation. Any conclusions drawn from analysis of the aforementioned data are the sole responsibility of the data recipient(s). Additionally, for coding years 2015 to present, the Bureau of Data Collection uses the exact latitude/longitude supplied by the investigating law enforcement agency to locate crashes. Therefore, location data may vary in previous years since data prior to 2015 was physically located by bureau personnel.