



Coordinate Collision Diagram Report

1/1/2014 to 12/31/2014

For XCoordinate 2138012.48802329 YCoordinate 1139316.9956419 Foot Tolerance : 250 County : Sangamon Intersection Related: Intersections *See Notes at End of Report.
--

Date	Weather	Roadway	Injuries			Killed	Type of Crash	Light Condition	Mile	XCordinate YCoordinate	Vehicle Type	DIRP	Maneuver	Event 1	Loc 1	Event 2	Loc 2	Event 3	Loc 3	Unit
201400063326																				
1/8/2014 8:11 AM	Clear	Ice	0	0	0	0	Angle	Daylight	0.00	2438012.50090642 1139316.46849243	Passenger	North	Straight Ahead	Motor Vehicle in n Traffic	Interseccio (UNK)	(UNK)	(UNK)	(UNK)	(UNK)	1
201400063316																				
1/8/2014 10:11 AM	Clear	Snow or Slush	0	0	0	0	Angle	Daylight	0.00	2438012.48802329 1139316.9956419	Passenger	North	Straight Ahead	Motor Vehicle in n Traffic	Interseccio (UNK)	(UNK)	(UNK)	(UNK)	(UNK)	1
201400033119																				
3/28/2014 2:49 PM	Clear	Dry	0	0	0	0	Turning	Daylight	0.00	2438012.49701855 1139316.6275757	Van/Mini-Van	Northwest	Turning Left	Motor Vehicle in Pavement Traffic	On (UNK)	(UNK)	(UNK)	(UNK)	(UNK)	1
201400219862																				
4/17/2014 10:15 AM	Cloudy/Overcast	Dry	0	0	0	0	Turning	Daylight	0.00	2438012.46262479 1139318.0348934	Passenger	South	Straight Ahead	Motor Vehicle in Pavement Traffic	On (UNK)	(UNK)	(UNK)	(UNK)	(UNK)	2
201400233478																				
5/14/2014 8:52 PM	Rain	Wet	0	0	2	0	Angle	Darkness, Lighted Road	0.00	2438012.50090642 1139316.46849243	Passenger	East	Straight Ahead	Motor Vehicle in n Traffic	Interseccio (UNK)	(UNK)	(UNK)	(UNK)	(UNK)	1
201400233478																				
5/14/2014 8:52 PM	Rain	Wet	0	0	2	0	Angle	Darkness, Lighted Road	0.00	2438012.50090642 1139316.46849243	SUV	North	Straight Ahead	Motor Vehicle in n Traffic	Interseccio (UNK)	Utility Pole	Off Pavement - Right	(UNK)	(UNK)	2



Coordinate Collision Diagram Report

1/1/2014 to 12/31/2014

For XCoordinate 2438012.48802329 : YCoordinate 1139316.9956419 | Foot Tolerance : 250 | County : Sangamon | Intersection Related: Intersections | *See Notes at End of Report.

Date	Weather	Roadway	Injuries			Killed	Type of Crash	Light Condition	Mile	XCoordinate	YCoordinate	Vehicle Type	DIRP	Maneuver	Event 1	Loc 1	Event 2	Loc 2	Event 3	Loc 3	Unit
201400434957			A	B	C																
11/9/2014 2:20 PM	Clear	Dry	0	0	0	0	Angle	Daylight	0.00	2438012.4971091	1139316.62387055	Passenger	East	Straight Ahead	Motor Vehicle In Pavement Traffic (Roadway)	On (UNK)	(UNK)	(UNK)	(UNK)	(UNK)	1
												Passenger	North	Straight Ahead	Motor Vehicle In Pavement Traffic (Roadway)	On (UNK)	(UNK)	(UNK)	(UNK)	(UNK)	2
201400442164																					
11/21/2014 10:06 PM	Rain	Wet	0	0	0	0	Turning	Darkness. Lighted Road	0.00	2438012.50090642	1139316.46849243	Passenger	Northwest	Turning Left	Motor Vehicle In Pavement Traffic (Roadway)	On (UNK)	(UNK)	(UNK)	(UNK)	(UNK)	1
												Passenger	South	Straight Ahead	Motor Vehicle In Pavement Traffic (Roadway)	On (UNK)	(UNK)	(UNK)	(UNK)	(UNK)	2



Coordinate Collision Diagram Report

1/1/2014 to 12/31/2014

For XCoordinate 2438012.48802329 : YCoordinate 1139316.9956419 | Foot Tolerance : 250 | County : Sangamon | Intersection Related: Intersections | *See Notes at End of Report.

TOTAL CRASHES	FATAL CRASHES	A INJURY CRASHES	B INJURY CRASHES	C INJURY CRASHES	PROPERTY DAMAGE CRASHES	TOTAL KILLED	TOTAL INJURED	A INJURIES	B INJURIES	C INJURIES
7	0	0	0	1	6	0	2	0	0	2

Type of Crash	Total	%	Day of Wk	Total	%	Hour of Day	Total	%	Vehicle Type	Total	%
Angle	4	57.1%	Wednesday	3	42.9%	09 AM	1	14.3%	Other	1	7.1%
Turning	3	42.9%	Thursday	1	14.3%	10 AM	2	28.6%	Passenger	10	71.4%
TOTAL:	7		Friday	2	28.6%	2 PM	2	28.6%	SUV	2	14.3%
			Sunday	1	14.3%	8 PM	1	14.3%	Van/Mini-Van	1	7.1%
			TOTAL:	7		10 PM	1	14.3%	TOTAL:	14	

Weather Cond	Total	%	Light Cond	Total	%	Road Surface	Total	%	DIRP	Total	%
Clear	4	57.1%	Darkness, Lighted Road	2	28.6%	Dry	3	42.9%	East	4	28.6%
Cloudy/Overcast	1	14.3%	Daylight	5	71.4%	Ice	1	14.3%	North	4	28.6%
Rain	2	28.6%	TOTAL:	7		Snow or Slush	1	14.3%	Northwest	2	14.3%
TOTAL:	7					Wet	2	28.6%	South	3	21.4%
						TOTAL:	7		West	1	7.1%
									TOTAL:	14	



Coordinate Collision Diagram Report

1/1/2014 to 12/31/2014

For XCoordinate 2438012.48802329 : YCoordinate 1139316.9956419 | Foot Tolerance : 250 | County : Sangamon | Intersection Related: Intersections | *See Notes at End of Report.

Notes

DISCLAIMER: The motor vehicle crash data referenced herein was provided by the Illinois Department of Transportation. Any conclusions drawn from analysis of the aforementioned data are the sole responsibility of the data recipient(s). Additionally, for coding years 2015 to present, the Bureau of Data Collection uses the exact latitude/longitude supplied by the investigating law enforcement agency to locate crashes. Therefore, location data may vary in previous years since data prior to 2015 was physically located by bureau personnel.



Coordinate Collision Diagram Report

1/1/2015 to 12/31/2015

For XCoordinate 2438012.48802329 : YCoordinate 1139316.9956419 | Foot Tolerance : 250 | County : Sangamon | Intersection Related: Intersections | *See Notes at End of Report.

Date	Weather	Roadway	A	Injuries B	C	Killed	Type of Crash	Light Condition	Mile	XCoordinate YCoordinate	Vehicle Type	DIRP	Maneuver	Event 1	Loc 1	Event 2	Loc 2	Event 3	Loc 3	Unit
201501169738																				
1/5/2015 5:14 PM	Snow	Snow or Slush	0	0	1	0	Turning	Darkness, Lighted Road	0.00	2438012.53437033 1139316.98717291	Passenger	Southeast	Turning Left	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
20150131855																				
7/31/2015 10:29 AM	Clear	Dry	0	1	0	0	Turning	Daylight	0.00	2438012.50090642 1139316.46849243	Passenger	East	Turning Left	Motor Vehicle In Traffic	Intersection (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
20150131855																				
9/3/2015 11:16 AM	Clear	Dry	0	1	0	0	Turning	Daylight	0.00	2438012.20500781 1139316.47107173	Passenger	West	Straight Ahead	Motor Vehicle In Traffic	Intersection (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
201501470949																				
9/30/2015 6:41 PM	Clear	Dry	0	0	0	0	Front to Rear	Daylight	0.00	2438012.09879399 1139316.47199758	Passenger	West	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
201501472977																				
11/17/2015 6:02 PM	Rain	Wet	0	1	0	0	Pedalcyclist	Darkness, Lighted Road	0.00	2438012.12912453 1139316.4717332	Passenger	North	Straight Ahead	Pedalcycl ist	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2



Coordinate Collision Diagram Report

1/1/2015 to 12/31/2015

For XCoordinate 2438012.48802329 : YCoordinate 1139316.9956419 | Foot Tolerance : 250 | County : Sangamon | Intersection Related: Intersections | *See Notes at End of Report.

Date	Weather	Roadway	Injuries			Killed	Type of Crash	Light Condition	Mile	XCoordinate	YCoordinate	Vehicle Type	DIRP	Maneuver	Event 1	Loc 1	Event 2	Loc 2	Event 3	Loc 3	Unit
201501493164			A	B	C																
12/15/2015 4:52 PM	Clear	Dry	0	0	0	0	Front to Rear	Darkness, Lighted Road	0.00	2438012.41634538	1139316.46922953	SUV	West	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
												Passenger	West	Slow/Stop In Traffic	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
												Passenger	West	Slow/Stop In Traffic	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	3



Coordinate Collision Diagram Report

1/1/2015 to 12/31/2015

For XCoordinate 2438012.48802329 : YCoordinate 1139316.9956419 | Foot Tolerance : 250 | County : Sangamon | Intersection Related: Intersections | *See Notes at End of Report.

TOTAL CRASHES	FATAL CRASHES	A INJURY CRASHES	B INJURY CRASHES	C INJURY CRASHES	PROPERTY DAMAGE CRASHES	TOTAL KILLED	TOTAL INJURED	A INJURIES	B INJURIES	C INJURIES
6	0	0	3	1	2	0	4	0	3	1

Type of Crash	Total	%	Day of Wk	Total	%	Hour of Day	Total	%	Vehicle Type	Total	%
Front to Rear	2	33.3%	Monday	1	16.7%	10 AM	1	16.7%	Passenger	10	76.9%
Pedalcyclist	1	16.7%	Tuesday	2	33.3%	11 AM	1	16.7%	SUV	1	7.7%
Turning	3	50.0%	Wednesday	1	16.7%	4 PM	1	16.7%	Van/Min-Van	2	15.4%
TOTAL:	6		Thursday	1	16.7%	5 PM	1	16.7%	TOTAL:	13	
			Friday	1	16.7%	6 PM	1	16.7%			
			TOTAL:	6		8 PM	1	16.7%			
			TOTAL:			TOTAL:	6				
Weather Cond	Total	%	Light Cond	Total	%	Road Surface	Total	%	DIRP	Total	%
Clear	4	66.7%	Darkness, Lighted Road	3	50.0%	Dry	4	66.7%	East	1	7.7%
Rain	1	16.7%	Daylight	3	50.0%	Snow or Slush	1	16.7%	North	2	15.4%
Snow	1	16.7%	TOTAL:	6		Wet	1	16.7%	Northeast	1	7.7%
TOTAL:	6					TOTAL:	6		Southeast	1	7.7%
									West	8	61.5%
									TOTAL:	13	



Coordinate Collision Diagram Report

1/1/2015 to 12/31/2015

For XCoordinate 2438012.48802329 : YCoordinate 1139316.9956419 | Foot Tolerance : 250 | County : Sangamon | Intersection Related: Intersections | *See Notes at End of Report.

Notes

DISCLAIMER: The motor vehicle crash data referenced herein was provided by the Illinois Department of Transportation. Any conclusions drawn from analysis of the aforementioned data are the sole responsibility of the data recipient(s). Additionally, for coding years 2015 to present, the Bureau of Data Collection uses the exact latitude/longitude supplied by the investigating law enforcement agency to locate crashes. Therefore, location data may vary in previous years since data prior to 2015 was physically located by bureau personnel.



Coordinate Collision Diagram Report

1/1/2016 to 12/31/2016

For XCoordinate 2438012.48802329 : YCoordinate 1139316.9956419 | Foot Tolerance : 250 | County : Sangamon | Intersection Related: Intersections | *See Notes at End of Report.

Date	Weather	Roadway	A	Injuries B	C	Killed	Type of Crash	Light Condition	Mile	XCoordinate YCoordinate	Vehicle Type	DIRP	Maneuver	Event 1	Loc 1	Event 2	Loc 2	Event 3	Loc 3	Unit
201601362053																				
3/18/2016 6:49 PM	Clear	Dry	0	0	1	0	Angle	Darkness, Lighted Road	0.00	2438012.56057447 1139316.46770408	Van/Mini- Van	West	Straight Ahead	Motor Vehicle In Traffic	Intersectio n	(UNK)	(UNK)	(UNK)	(UNK)	1
											Van/Mini- Van	North	Straight Ahead	Motor Vehicle In Traffic	Intersectio n	(UNK)	(UNK)	(UNK)	(UNK)	2
201601380865																				
4/13/2016 8:11 AM	Clear	Dry	0	0	0	0	Turning	Daylight	0.00	2438012.62062431 1139316.46691069	Passenger	South	Turning Left	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
											Passenger	North	Unknown	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
201601384560																				
4/22/2016 7:55 AM	Clear	Dry	0	0	0	0	Turning	Daylight	0.00	2438012.50090642 1139316.46849243	Passenger	West	Turning Left	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
											Passenger	South	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
201601384235																				
4/24/2016 1:18 PM	Clear	Dry	0	0	0	0	Front to Rear	Daylight	0.00	2438012.50090642 1139316.46849243	Van/Mini- Van	East	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
											Passenger	East	Slow/Stop - Left Turn	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
201601413631																				
6/30/2016 3:03 PM	Clear	Dry	1	0	0	0	Turning	Daylight	0.00	2438012.5922102 1139316.4672861	Passenger	South	Turning Left	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
											Passenger	North	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2



Coordinate Collision Diagram Report

1/1/2016 to 12/31/2016

For XCoordinate 2438012.48802329 : YCoordinate 1139316.9956419 | Foot Tolerance : 250 | County : Sangamon | Intersection Related: Intersections | *See Notes at End of Report.

Date	Weather	Roadway	Injuries			Killed	Type of Crash	Light Condition	Mile	XCoordinate	Vehicle Type	DIRP	Maneuver	Event 1	Loc 1	Event 2	Loc 2	Event 3	Loc 3	Unit
			A	B	C															
201601428658																				
7/5/2016 3:19 PM	Clear	Dry	0	0	0	0	Angle	Daylight	0.00	2438012.50090642 1139316.46849243	Passenger West	Unknown	Unknown	Motor Vehicle In n Traffic	Intersectio	(UNK)	(UNK)	(UNK)	(UNK)	1
201601441312																				
8/12/2016 7:45 AM	Clear	Dry	0	0	0	0	Turning	Daylight	0.00	2438012.50090642 1139316.46849243	Passenger South	Turning Left	Turning Left	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
201601447147																				
8/31/2016 2:27 PM	Clear	Dry	0	1	0	0	Turning	Daylight	0.00	2438012.50090642 1139316.46849243	Passenger North	Unknown	Unknown	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
201601463434																				
9/30/2016 1:30 PM	Rain	Wet	1	0	0	0	Turning	Daylight	0.00	2438012.50090642 1139316.46849243	Passenger Northeast	Turning Left	Turning Left	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
201601477265																				
10/18/2016 7:58 AM	Clear	Dry	0	0	0	0	Turning	Daylight	0.00	2438012.61954612 1139316.46892494	Passenger West	Turning Left	Turning Left	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
201601477265																				
10/18/2016 7:58 AM	Clear	Dry	0	0	0	0	Turning	Daylight	0.00	2438012.61954612 1139316.46892494	Passenger South	Turning Left	Turning Left	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2



Coordinate Collision Diagram Report

1/1/2016 to 12/31/2016

For XCoordinate 2438012.48802329 : YCoordinate 1139316.9956419 | Foot Tolerance : 250 | County : Sangamon | Intersection Related: Intersections | *See Notes at End of Report.

TOTAL CRASHES	FATAL CRASHES	A INJURY CRASHES	B INJURY CRASHES	C INJURY CRASHES	PROPERTY DAMAGE CRASHES	TOTAL KILLED	TOTAL INJURED	A INJURIES	B INJURIES	C INJURIES
10	0	2	1	1	6	0	4	2	1	1

Type of Crash	Total	%	Day of Wk	Total	%	Hour of Day	Total	%	Vehicle Type	Total	%
Angle	2	20.0%	Tuesday	2	20.0%	07 AM	3	30.0%	Passenger	14	70.0%
Front to Rear	1	10.0%	Wednesday	2	20.0%	08 AM	1	10.0%	Pickup	3	15.0%
Turning	7	70.0%	Thursday	1	10.0%	1 PM	2	20.0%	Van/Mini-Van	3	15.0%
TOTAL:	10		Friday	4	40.0%	2 PM	1	10.0%	TOTAL:	20	
			Sunday	1	10.0%	3 PM	2	20.0%			
			TOTAL:	10		6 PM	1	10.0%			
			TOTAL:	10							

Weather Cond	Total	%	Light Cond	Total	%	Road Surface	Total	%	DIRP	Total	%
Clear	9	90.0%	Darkness, Lighted Road	1	10.0%	Dry	9	90.0%	East	2	10.0%
Rain	1	10.0%	Daylight	9	90.0%	Wet	1	10.0%	North	6	30.0%
TOTAL:	10		TOTAL:	10		TOTAL:	10		Northeast	1	5.0%
									South	5	25.0%
									Southeast	1	5.0%
									West	5	25.0%
									TOTAL:	20	



Coordinate Collision Diagram Report

1/1/2016 to 12/31/2016

For XCoordinate 2438012.48802329 : YCoordinate 1139316.9956419 | Foot Tolerance : 250 | County : Sangamon | Intersection Related: Intersections | *See Notes at End of Report.

Notes

DISCLAIMER: The motor vehicle crash data referenced herein was provided by the Illinois Department of Transportation. Any conclusions drawn from analysis of the aforementioned data are the sole responsibility of the data recipient(s). Additionally, for coding years 2015 to present, the Bureau of Data Collection uses the exact latitude/longitude supplied by the investigating law enforcement agency to locate crashes. Therefore, location data may vary in previous years since data prior to 2015 was physically located by bureau personnel.



Coordinate Collision Diagram Report

1/1/2017 to 12/31/2017

For XCoordinate 2438012.48802329 : YCoordinate 1139316.9956419 | Foot Tolerance : 250 | County : Sangamon | Intersection Related: Intersections | *See Notes at End of Report.

Date	Weather	Roadway	A	Injuries B	C	Killed	Type of Crash	Light Condition	Mile	XCoordinate YCoordinate	Vehicle Type	DIRP	Maneuver	Event 1	Loc 1	Event 2	Loc 2	Event 3	Loc 3	Unit
201701389733																				
3/16/2017 5:41 PM	Clear	Dry	0	0	0	0	Turning	Daylight	0.00	2438012.50090642 1139316.46849243	SUV	West	Turning Left	Motor Vehicle In Traffic	On (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
											Passenger	South	Straight Ahead	Motor Vehicle In Traffic	On (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
201701406682																				
4/19/2017 3:49 PM	Clear	Dry	0	0	0	0	Turning	Daylight	0.00	2438012.50090642 1139316.46849243	Passenger	South	Turning Left	Motor Vehicle In Traffic	On (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
											SUV	North	Straight Ahead	Motor Vehicle In Traffic	On (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
201701425075																				
5/29/2017 4:06 PM	Clear	Dry	0	0	0	0	Turning	Daylight	0.00	2438012.50090642 1139316.46849243	Passenger	Northwest	Turning Left	Motor Vehicle In Traffic	On (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
											Passenger	South	Straight Ahead	Motor Vehicle In Traffic	On (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
201701429654																				
6/8/2017 11:41 PM	Clear	Dry	0	0	0	0	Front to Rear	Darkness, Lighted Road	0.00	2438012.50090642 1139316.46849243	SUV	East	Straight Ahead	Motor Vehicle In Traffic	On (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
											SUV	East	Slow/Stop In Traffic	Motor Vehicle In Traffic	On (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
201701442874																				
7/13/2017 5:51 PM	Clear	Dry	0	0	0	0	Angle	Daylight	0.00	2438012.50097704 1139315.65161925	SUV	East	Straight Ahead	Motor Vehicle In Traffic	Intersecto n	(UNK)	(UNK)	(UNK)	(UNK)	1
											Pickup	North	Straight Ahead	Motor Vehicle In Traffic	Intersecto n	(UNK)	(UNK)	(UNK)	(UNK)	2
											Passenger	West	Slow/Stop In Traffic	Motor Vehicle In Traffic	On (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	3



Coordinate Collision Diagram Report

1/1/2017 to 12/31/2017

For XCoordinate 2438012.48802329 : YCoordinate 1139316.9956419 | Foot Tolerance : 250 | County : Sangamon | Intersection Related: Intersections | *See Notes at End of Report.

Date	Weather	Roadway	Injures			Killed	Type of Crash	Light Condition	Mile	XCoordinate	Vehicle Type	DIRP	Maneuver	Event 1	Loc 1	Event 2	Loc 2	Event 3	Loc 3	Unit
201701423830			A	B	C															
10/6/2017 5:13 PM	Rain	Wet	0	0	0	0	Angle	Daylight	0.00	2438012.50090642 1139316.46849243	Passenger	North	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
											Passenger	East	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
201701477190																				
11/13/2017 1:35 PM	Clear	Dry	0	0	0	0	Angle	Daylight	0.00	2438012.50323339 1139316.25659633	Passenger	East	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
											Pickup	North	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
201701478020																				
11/16/2017 2:17 PM	Clear	Dry	0	0	0	0	Front to Rear	Daylight	0.00	2438012.50124353 1139316.43779455	Passenger	North	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
											SUV	North	Slow/Stop - Left Turn	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
201701478261																				
11/17/2017 4:43 PM	Clear	Dry	0	0	0	0	Turning	Daylight	0.00	2438012.50090642 1139316.46849243	Passenger	Southeast	Turning Left	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
											Passenger	North	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
201701473119																				
10/27/2017 3:47 PM	Clear	Dry	0	0	0	0	Front to Rear	Daylight	2.40	2438112.58168973 1139315.14620785	SUV	West	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
											Passenger	West	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
											SUV	West	Slow/Stop In Traffic	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	3



Coordinate Collision Diagram Report

1/1/2017 to 12/31/2017

For XCoordinate 2438012.48802329 : YCoordinate 1139316.9956419 | Foot Tolerance : 250 | County : Sangamon | Intersection Related: Intersections | *See Notes at End of Report.

Date	Weather	Roadway	Injuries			Killed	Type of Crash	Light Condition	Mile	XCoordinate	YCoordinate	Vehicle Type	DIRP	Maneuver	Event 1	Loc 1	Event 2	Loc 2	Event 3	Loc 3	Unit
201701488073			---	A	B	---	C														
12/27/2017 5:16 PM	Clear	Dry	0	0	0	0	Front to Rear	Darkness, Lighted Road	2.40	2438112.08396043	1139315.15278393	SUV	West	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
												Passenger	West	Slow/Stop In Traffic	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2



Coordinate Collision Diagram Report

1/1/2017 to 12/31/2017

For XCoordinate 2438012.48802329 : YCoordinate 1139316.9956419 | Foot Tolerance : 250 | County : Sangamon | Intersection Related: Intersections | *See Notes at End of Report.

TOTAL CRASHES	FATAL CRASHES	A INJURY CRASHES	B INJURY CRASHES	C INJURY CRASHES	PROPERTY DAMAGE CRASHES	TOTAL KILLED	TOTAL INURED	A INJURIES	B INJURIES	C INJURIES
11	0	0	0	0	11	0	0	0	0	0

Type of Crash	Total	%	Day of Wk	Total	%	Hour of Day	Total	%	Vehicle Type	Total	%
Angle	3	27.3%	Monday	2	18.2%	1 PM	1	9.1%	Passenger	13	54.2%
Front to Rear	4	36.4%	Wednesday	2	18.2%	2 PM	1	9.1%	Pickup	2	8.3%
Turning	4	36.4%	Thursday	4	36.4%	3 PM	2	18.2%	SUV	9	37.5%
TOTAL:	11		Friday	3	27.3%	4 PM	2	18.2%	TOTAL:	24	
			TOTAL:	11		5 PM	4	36.4%			
						11 PM	1	9.1%			
						TOTAL:	11				

Weather Cond	Total	%	Light Cond	Total	%	Road Surface	Total	%	DIRP	Total	%
Clear	10	90.9%	Darkness, Lighted Road	2	18.2%	Dry	10	90.9%	East	5	20.8%
Rain	1	9.1%	Daylight	9	81.8%	Wet	1	9.1%	North	7	29.2%
TOTAL:	11		TOTAL:	11		TOTAL:	11		Northwest	1	4.2%
									South	3	12.5%
									Southeast	1	4.2%
									West	7	29.2%
									TOTAL:	24	



Coordinate Collision Diagram Report

1/1/2017 to 12/31/2017

For XCoordinate 2438012.48802329 : YCoordinate 1139316.9956419 | Foot Tolerance : 250 | County : Sangamon | Intersection Related: Intersections | *See Notes at End of Report.

Notes

DISCLAIMER: The motor vehicle crash data referenced herein was provided by the Illinois Department of Transportation. Any conclusions drawn from analysis of the aforementioned data are the sole responsibility of the data recipient(s). Additionally, for coding years 2015 to present, the Bureau of Data Collection uses the exact latitude/longitude supplied by the investigating law enforcement agency to locate crashes. Therefore, location data may vary in previous years since data prior to 2015 was physically located by bureau personnel.



Coordinate Collision Diagram Report

1/1/2018 to 12/31/2018

For XCoordinate 2438012.48802329 : YCoordinate 1139316.9956419 | Foot Tolerance : 250 | County : Sangamon | Intersection Related: Intersections | *See Notes at End of Report.

Date	Weather	Roadway	Injuries			Killed	Type of Crash	Light Condition	Mile	XCoordinate	YCoordinate	Vehicle Type	DIRP	Maneuver	Event 1	Loc 1	Event 2	Loc 2	Event 3	Loc 3	Unit
			A	B	C																
201801433491																					
4/13/2018 1:30 PM	Cloudy/Overcast	Dry	0	0	0	0	Angle	Daylight	0.00	2438012.50119686	1139316.44204436	Passenger	North	Straight Ahead	Motor Vehicle In Pavement Traffic	On (Roadway)	Other Object - Right	(UNK)	(UNK)		1
												Passenger	East	Straight Ahead	Motor Vehicle In Pavement Traffic	On (Roadway)	(UNK)	(UNK)	(UNK)		2
201801442946																					
5/24/2018 9:50 AM	Clear	Dry	0	0	1	0	Angle	Daylight	0.00	2438012.50090642	1139316.46849243	Passenger	North	Straight Ahead	Motor Vehicle In Pavement Traffic	On (Roadway)	(UNK)	(UNK)	(UNK)		1
												Passenger	West	Straight Ahead	Motor Vehicle In Pavement Traffic	On (Roadway)	(UNK)	(UNK)	(UNK)		2
201801467327																					
9/14/2018 5:01 PM	Clear	Dry	0	0	0	0	Angle	Daylight	0.00	2438012.50090642	1139316.46849243	Passenger	East	Straight Ahead	Motor Vehicle In Pavement Traffic	On (Roadway)	(UNK)	(UNK)	(UNK)		1
												Pickup	South	Straight Ahead	Motor Vehicle In Pavement Traffic	On (Roadway)	(UNK)	(UNK)	(UNK)		2
201801484606																					
11/14/2018 9:13 AM	Clear	Dry	0	0	0	0	Angle	Daylight	0.00	2438012.50349937	1139316.23237549	Passenger	East	Straight Ahead	Motor Vehicle In Pavement Traffic	Intersection	(UNK)	(UNK)	(UNK)		1
												Pickup	North	Straight Ahead	Motor Vehicle In Pavement Traffic	(UNK)	(UNK)	(UNK)	(UNK)		2
201801434171																					
4/16/2018 4:40 PM	Clear	Dry	0	0	1	0	Front to Rear	Daylight	2.40	2438092.18630672	1139315.41567517	SUV	West	Straight Ahead	Motor Vehicle In Pavement Traffic	On (Roadway)	(UNK)	(UNK)	(UNK)		1
												Passenger	West	Slow/Stop In Traffic	Motor Vehicle In Pavement Traffic	On (Roadway)	(UNK)	(UNK)	(UNK)		2



Coordinate Collision Diagram Report

1/1/2018 to 12/31/2018

For XCoordinate 2438012.48802329 : YCoordinate 1139316.9956419 | Foot Tolerance : 250 | County : Sangamon | Intersection Related: Intersections | *See Notes at End of Report.

TOTAL CRASHES	FATAL CRASHES	A INJURY CRASHES	B INJURY CRASHES	C INJURY CRASHES	PROPERTY DAMAGE CRASHES	TOTAL KILLED	TOTAL INJURED	A INJURIES	B INJURIES	C INJURIES
5	0	0	0	2	3	0	2	0	0	2

Type of Crash	Total	%	Day of Wk	Total	%	Hour of Day	Total	%	Vehicle Type	Total	%
Angle	4	80.0%	Monday	1	20.0%	09 AM	2	40.0%	Passenger	7	70.0%
Front to Rear	1	20.0%	Wednesday	1	20.0%	1 PM	1	20.0%	Pickup	2	20.0%
TOTAL:	5		Thursday	1	20.0%	4 PM	1	20.0%	SUV	1	10.0%
			Friday	2	40.0%	5 PM	1	20.0%	TOTAL:	10	
			TOTAL:	5		TOTAL:	5				
Weather Cond	Total	%	Light Cond	Total	%	Road Surface	Total	%	DIRP	Total	%
Clear	4	80.0%	Daylight	5	100.0%	Dry	5	100.0%	East	3	30.0%
Cloudy/Overcast	1	20.0%	TOTAL:	5		TOTAL:	5		North	3	30.0%
TOTAL:	5								South	1	10.0%
									West	3	30.0%
									TOTAL:	10	



Coordinate Collision Diagram Report

1/1/2018 to 12/31/2018

For XCoordinate 2438012.48802329 : YCoordinate 1139316.9956419 | Foot Tolerance : 250 | County : Sangamon | Intersection Related: Intersections | *See Notes at End of Report.

Notes

DISCLAIMER: The motor vehicle crash data referenced herein was provided by the Illinois Department of Transportation. Any conclusions drawn from analysis of the aforementioned data are the sole responsibility of the data recipient(s). Additionally, for coding years 2015 to present, the Bureau of Data Collection uses the exact latitude/longitude supplied by the investigating law enforcement agency to locate crashes. Therefore, location data may vary in previous years since data prior to 2015 was physically located by bureau personnel.